

FORM INSP Rev X/20	State of Colorado Energy and Carbon Management Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>09/29/2025</u> Submitted Date: <u>09/29/2025</u> Document Number: <u>719000703</u>
FIELD INSPECTION FORM			

Loc ID <u>326611</u> Inspector Name: <u>GARCIA, CHARLES</u> On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: ECMC Operator Number: <u>10749</u> Name of Operator: <u>SIMCOE LLC</u> Address: <u>1199 MAIN AVE SUITE 101</u> City: <u>DURANGO</u> State: <u>CO</u> Zip: <u>81301</u>		Findings: <u>15</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE		

Contact Information:			
Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All Inspections

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258939	WELL	PR	04/13/2001	CBM	067-08393	MILLER FEDERAL 2	PR

General Comment:

[Inspection Report Summary](#)
 On 09/29/25 | Inspector Charles Garcia conducted an on-site inspection.
 Location: MILLER FEDERAL 2
 Operator: Simcoe LLC
 API#: 067-08383
 County: LaPlata

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTERANCE		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	PRDUCED WATER TANK		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Contact # 970-247-6916 Emergency #911		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Type	OTHER		
Comment:	PRODUCED WATER TANK CATTLE PANELS		
Corrective Action:			Date:
Type	OTHER		
Comment:	METER HOUSE CATTLE PANELS		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	CATTLE PANELS		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		

Comment:	ELECTRIC		Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	METER HOUSE CALIBRATION IN COMPLIANCE		Date:	
Corrective Action:			Date:	
Type: Flow Line	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Vertical Heated Separator	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 3			
Comment:	ELECTRIC PANELS TELEMETRY WQUIPMENT		Date:	
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	WELLHEAD		Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 1			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.262100,-107.639300
Comment:	95 BBL PRODUCED WATER TANK				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment:		
Corrective Action:		Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 258939 Type: WELL API Number: 067-08393 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/11/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000709	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7259500