

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2025

Submitted Date:

10/01/2025

Document Number:

715202996

**FIELD INSPECTION FORM**

Loc ID 321245 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 83130  
Name of Operator: STRACHAN EXPLORATION INC  
Address: 992 S 4TH AVE SUITE 100-461  
City: BRIGHTON State: CO Zip: 80601

**Findings:**

9 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Reed, Shawn	303-562-6530	shawn@sreedconsulting.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281172	WELL	PR	05/01/2017	GW	011-06179	SEMMENS 2	PR

**General Comment:**

[This is a field audit of the scout card, related documents and the location conducted by SE Compliance Specialist Brian Welsh](#)

**Location**

**Lease Road:**

Type	Access		
comment:	Two track through pasture		
Corrective Action			Date:

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Sticker and stencil on water tank		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Lease sign mounted to meter shed. Add new sticker for current operator		
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Pipe fence around wellhead		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Wire fence around water tank. Fence is in disrepair		
Corrective Action:	Repair fence		Date: 10/24/2025

**Equipment:**

			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Meter shed on east side of location		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		38.254960,-102.754030

Comment:	Fiberglass open top water tank on east side of wellhead	
Corrective Action:		Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	160bbbs
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 281172 Type: WELL API Number: 011-06179 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715203041	location overview	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7263285">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7263285</a>