

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2025

Submitted Date:

10/01/2025

Document Number:

715203000

**FIELD INSPECTION FORM**

Loc ID 321237 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 83130  
Name of Operator: STRACHAN EXPLORATION INC  
Address: 992 S 4TH AVE SUITE 100-461  
City: BRIGHTON State: CO Zip: 80601

**Findings:**

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Reed, Shawn	303-562-6530	shawn@sreedconsulting.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206420	WELL	PR	09/01/2023	GW	011-06167	HUMPHREY-WOLLERT 2	PR

**General Comment:**

[This is a field audit of the scout card, related documents and the location conducted by SE Compliance Specialist Brian Welsh](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Dirt road through pasture		
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by wellhead		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Lease sign on west side of meter shed. Sign isnt legible		
Corrective Action:	Install sign to comply with Rule 605.a.	Date:	10/24/2025

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Wire fence around old tank battery and meter shed		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Pipe fence around wellhead		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type:	Gas Meter Run	# 1	
Comment:	Meter shed on SE corner of tank battery inside fence		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			

Comment:		
Corrective Action:	Date:	

**Inspected Facilities**

Facility ID: 206420 Type: WELL API Number: 011-06167 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715203036	wellhead photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7263289">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7263289</a>
715203037	meter shed	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7263290">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7263290</a>