

FORM
INSPRev
X/20

State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/01/2025

Submitted Date:

10/01/2025

Document Number:

719000730

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
325921 _____ GARCIA, CHARLES _____ 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|-------|-------------------------------|---------------------------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| , General | | sjninspections@ikavenergy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 215570 | WELL | PR | 12/31/2015 | CBM | 067-07175 | CUNDIFF FEDERAL A 1 | PR |

General Comment:

[Inspection Report Summary](#)
On 10/1/25 | Inspector Charles Garcia
conducted an on-site inspection.
Location: CUNDIFF FEDERAL A#1
Operator: Simcoe LLC
API#: 067-07175
County: LaPlata

| Location | | | |
|--|--|--------|--------------------------------------|
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | OTHER | | |
| Comment: | LOCATION SIGN AT ENTERANCE | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | 24 Hr #970-247-6916 Emergency #911 | | |
| Corrective Action: | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | OTHER | | |
| Comment: | WELLHEAD METER HOUSE DEHYDRATOR CATTLE PANELS | | |
| Corrective Action: | | | Date: |
| Type | PUMP JACK | | |
| Comment: | CATTLE PANELS | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Prime Mover | | | # 1 |
| Comment: | | | GAS |
| Corrective Action: | | | Date: |
| Type: Other | | | # 1 |
| Comment: | | | METERHOUSE CALIBRATION IN COMPLIANCE |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | | | # 2 |
| Comment: | | | TELEMETRY EQUIPMENT |
| Corrective Action: | | | Date: |
| Type: Dehydrator | | | # 1 |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | | | # 1 |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|---------------------|-----|-------|--|
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |
| Compaction | Pass | Compaction | Pass | | | |
| Check Dams | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 719000736 | LOCATION PICTURES | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7263869 |