

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/01/2025

Submitted Date:

10/01/2025

Document Number:

698708132

FIELD INSPECTION FORM

Loc ID 308100 Inspector Name: Serna, Abe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,	719-846-7898	cogcc.evergreen@enrllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261607	WELL	PR	04/01/2025	CBM	071-07518	LOVATO 14-20	PR

General Comment:

[Frac Inspection](#)

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Well sign on meter house		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 261607 Type: WELL API Number: 071-07518 Status: PR Insp. Status: PR

Well Stimulation

Stimulation Company: ENR Stimulation Type: HYDRAULIC FRAC
 Other: _____

Observation:

Maximum Casing Recorded: _____ PSI Tubing: _____
 Surface: _____ Intermediate: _____
 Production: _____ Instantaneous Shut-In Pressure (ISIP) _____
 Bradenhead Psi: _____ Frac Flow Back: Fluid: _____ Gas: _____

Comment: ENR Frac crew was in the process of fracing stage 11

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<u>Routine Frac Inspection</u> <u>Drive time to & from location 3 Hrs</u>	sernaa	10/01/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698708133	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7263895