

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/22/2025

Submitted Date:

09/25/2025

Document Number:

717701714

**FIELD INSPECTION FORM**

Loc ID 428521 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 8960  
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202

**Findings:**

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428523	WELL	SI	07/01/2023	OW	123-35394	Park T-P-4HZ	SI
431640	WELL	SI	06/01/2025	OW	123-36709	Park 44-41-4HNB	SI
435422	WELL	PR	05/01/2025	OW	123-38605	Park O-K-4HC	PR
435423	WELL	PR	06/01/2025	OW	123-38606	Park T-P-4HC	PR

**General Comment:**

[This is an audit of the scout card and related documents followed by a field audit.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate	Date:	
Corrective Action:			

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused pumping unit and equipment laying around the Park T-P-4HZ needs to be removed for good housekeeping. See attached photos		
Corrective Action:	Comply with Rule 606	Date:	12/31/2025

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

**Equipment:**

Type			corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Unused equipment		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
------	--	--	--

Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 428523 Type: WELL API Number: 123-35394 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI  
Form 06A on file

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 11/15/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 431640 Type: WELL API Number: 123-36709 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 12/30/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE  
End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 435422 Type: WELL API Number: 123-38605 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 12/30/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE  
End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 435423 Type: WELL API Number: 123-38606 Status: PR Insp. Status: PR

**Producing Well**

Comment:	<a href="#">PR</a>	Date:	
Corrective Action:			

**BradenHead**

Date of Last Brhd Test: 12/30/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><a href="#">ECMC Audit Report Summary</a></p> <p>On Monday, September 22, 2025, at approximately 8:47 PM, Inspector Adam Burns conducted an on-site audit to the following location:</p> <p>Location: Park T-4 Pad                      Operator: Civitas                      Location ID #428521                      County: Weld</p> <p>During the audit, the following possible compliance issues were identified:                      Unused pumping unit and equipment laying around the Park T-P-4HZ needs to be removed for good housekeeping. Comply with Rule 606. CA date of 12/31/25                      A follow-up audit is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules.                      Please note that any corrective actions from previous audits that have not been addressed remain applicable.</p>	burnsa	09/25/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404368931	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7254527">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7254527</a>
717701715	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7254522">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7254522</a>