

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/30/2025

Submitted Date:

10/02/2025

Document Number:

719700146

FIELD INSPECTION FORM

Loc ID 420534 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420504	WELL	TA	05/14/2020	OW	123-32601	Gabel USX AB21-14	TA

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location

Lease Road:

Type	Access				
comment:	Adequate				
Corrective Action:				Date:	

Overall Good:

Signs/Marker:

Type	WELLHEAD				
Comment:	OOSLAT tag posted at well.				
Corrective Action:				Date:	

Emergency Contact Number:

Comment:	Posted. *Emergency contact label is peeling. Recommend replacement.			
Corrective Action:				Date:

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD				
Comment:	Iron panel.				
Corrective Action:				Date:	

Equipment:

					corrective date
Type: Bradenhead	# 1				
Comment:	Appears plumbed to surface.				
Corrective Action:				Date:	
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO				
Comment:					
Corrective Action:				Date:	

Flaring:

Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 420504 Type: WELL API Number: 123-32601 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Battery Abandoned.
Locked-Out, Tagged-Out | LOTO.
OOSLAT tag(s) posted at well.
ECMC records last production: 12/2016.

Form 4 on file. TA Date: 01/18/2019.
Defined Inactive: 08/31/2016.
Form 6A on file. Out-of-Svc Designation.
Date: 08/01/2016. Approved.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 06/12/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
<p>CECMC Audit Report Synopsis:</p> <p>On TUE 09/30/2025 at approximately 12:43 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: NOBLE ENERGY INC Location Name: Gabel USX/AB21-14 Location ID: 420534 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.554809 / -104.563667</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	10/02/2025
<p>This is a WELL inspection. Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.554809 / -104.563667</p> <p>Abandoned Centralized Battery formerly served 3 Location IDs (417660, 420534, 306293). (Well(s): 2: Temporarily Abandoned TA ; 1: Plugged & Abandoned PA).</p> <p>Reference (Associated Well(s), Battery Inspections): A.) Field Inspection Report doc. #719700144 and/or Location ID #417660 for TA Well(s) info. B.) Field Inspection Report doc. #719700146 and/or Location ID #420534 for TA Well(s) info. C.) Field Inspection Report doc. #719700148 and/or Location ID #306293 for PA Well(s) info.</p>	evinsb	10/02/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700147	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7265472