

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/30/2025

Submitted Date:

10/02/2025

Document Number:

719700148

FIELD INSPECTION FORM

Loc ID: 306293 Inspector Name: Evins, Bret On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287599	WELL	PA	10/09/2023	OW	123-24372	GABEL USX AB 21-11	PA

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume	corrective date
Plunger Lift	# 0		
Comment: Plugged & Abandoned PA. Equipment removed.			
Corrective Action:			Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 287599 Type: WELL API Number: 123-24372 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Audit Report Synopsis:</p> <p>On TUE 09/30/2025 at approximately 13:07 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: NOBLE ENERGY INC Location Name: GABEL USX AB-67N64W/21NESW Location ID: 306293 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.554809 / -104.563667</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 6-SRA on file. Plugging, cut/cap date: 10/09/2023. Approved. Plugged & Abandoned PA well GPS coordinates: 40.557330 / -104.556550</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	10/02/2025
<p>This is a PLUGGED & ABANDONED WELL inspection. Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.554809 / -104.563667</p> <p>Abandoned Centralized Battery formerly served 3 Location IDs (417660, 420534, 306293). (Well(s): 2: Temporarily Abandoned TA ; 1: Plugged & Abandoned PA).</p> <p>Reference (Associated Well(s), Battery Inspections): A.) Field Inspection Report doc. #719700144 and/or Location ID #417660 for TA Well(s) info. B.) Field Inspection Report doc. #719700146 and/or Location ID #420534 for TA Well(s) info. C.) Field Inspection Report doc. #719700148 and/or Location ID #306293 for PA Well(s) info.</p>	evinsb	10/02/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700149	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7265473