

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/30/2025

Submitted Date:

10/02/2025

Document Number:

719700156

FIELD INSPECTION FORM

Loc ID 420555 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_ecmc_engineering@state.co.us	
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420537	WELL	TA	05/15/2020	OW	123-32610	Mojack USX AB21-15	PA

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume	corrective date
Plunger Lift	# 0		
Comment: Plugged & Abandoned PA. Equipment removed.			
Corrective Action:			Date:

Venting:

Yes/No		
Comment:	<input type="text"/>	
Corrective Action:		Date:

Flaring:

Type	
Comment:	<input type="text"/>
Corrective Action:	Date:

Inspected Facilities

Facility ID: 420537 Type: WELL API Number: 123-32610 Status: TA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Audit Report Synopsis:</p> <p>On TUE 09/30/2025 at approximately 14:26 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: NOBLE ENERGY INC Location Name: Mojack USX/AB21-15 Location ID: 420555 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.551449 / -104.549991</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 6-SRA on file. Plugging, cut/cap date: 07/02/2025. Approval Pending. Plugged & Abandoned PA well GPS coordinates: 40.552900 / -104.551640 Form 27 on file. Approved.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	10/02/2025
<p>This is a PLUGGED & ABANDONED WELL inspection. Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.551449 / -104.549991</p> <p>Abandoned Centralized Battery formerly served 3 Location IDs (420555, 410100, 410151). (Well(s): 3: Plugged & Abandoned PA).</p> <p>Reference (Associated Well(s), Battery Inspections): A.) Field Inspection Report doc. #719700156 and/or Location ID #420555 for PA Well(s) info. B.) Field Inspection Report doc. #719700158 and/or Location ID #410100 for PA Well(s) info. C.) Field Inspection Report doc. #719700160 and/or Location ID #410151 for PA Well(s) info.</p>	evinsb	10/02/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700157	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7265477