

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/30/2025

Submitted Date:

10/02/2025

Document Number:

719700166

**FIELD INSPECTION FORM**

Loc ID 424867 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

16 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424860	WELL	SI	07/01/2024	OW	123-34197	Irvine 15-22	SI

**General Comment:**

\*This is an audit of the scout card and related documents followed by a field audit.

**Location**

<b>Lease Road:</b>			
	Type Access		
comment:	Adequate		
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type WELLHEAD		
Comment:	OOSLAT applied at wellsite(s), separator.		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
	Comment: Posted.		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
	Type WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Emission Control Device	# 0		
Comment:	Equipment assigned to Fac ID #445768.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 0		
Comment:	Equipment assigned to Fac ID #445768.		
Corrective Action:			Date:
Type: Gas Meter Run	# 0		
Comment:	Equipment assigned to Fac ID #445768.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

<b>Tanks and Berms:</b>						
Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.551673,-104.533053	
Comment:	Centralized Battery serves 2 Location IDs (424867, 424863). (Well(s): 2: Shut-In   SI). Centralized Battery serves 1 Tank Battery Facility ID (445768).					
Corrective Action:					Date:	

<b>Paint</b>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						

<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0				,	
Comment:	Equipment assigned to Fac ID #445768.					
Corrective Action:					Date:	

<b>Paint</b>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						

<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0				,	
Comment:	Equipment assigned to Fac ID #445768.					
Corrective Action:					Date:	

<b>Paint</b>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:

<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 424860 Type: WELL API Number: 123-34197 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut-In | SI.  
Prod valves shut.  
Locked-Out, Tagged-Out | LOTO.  
OOSLAT applied at well, separator.  
ECMC records last prod: 06/2024.  
  
Common / Shared flowline w/ Irvine 20-22.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 02/02/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width:100%;" type="text"/> Corrective Action: <input style="width:100%;" type="text"/>						Date: _____
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

**ECMC Comments**

Comment	User	Date
<p><b>CECMC Audit Report Synopsis:</b></p> <p>On TUE 09/30/2025 at approximately 15:35 hrs. I, Bret Evins, conducted an onsite audit at:                      Operator Name: PDC ENERGY INC                      Location Name: Irvine/15-22                      Location ID: 424867                      Well Name(s) &amp; API:                      Reference:                      See "Inspected Facilities" section on page 1 of this report.                      Location County: Weld County, Colorado                      Weather: Mostly Sunny, dry.</p> <p>While there, I observed:                      Well(s): 1: Shut-In  SI.                      Battery: Inactive   Shut-down.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	10/02/2025
<p>This is a WELL audit.                      Well(s): 1: Shut-In   SI.                      Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (424867, 424863).                      (Well(s): 2: Shut-In   SI).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (445768).</p> <p>Reference (Associated Well(s), Battery / Facility Audits):                      A.) Field Audit Report doc. #719700166 and/or Location ID #424867 for SI Well(s) info.                      B.) Field Audit Report doc. #719700168 and/or Location ID #424863 for SI Well(s) info.                      C.) Field Audit Report doc. #719700170 and/or Facility ID #445768 for Battery / Facility, Equipment info.</p>	evinsb	10/02/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700167	Audit photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7265482">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7265482</a>