

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/01/2025

Submitted Date:

10/03/2025

Document Number:

717300496

FIELD INSPECTION FORM

Loc ID 306712 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		Inspections@civiresources.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290602	WELL	SI	11/01/2023	OW	123-25148	ELLIOT - USX S 31-10	PA
452637	LOCATION	AC			-	Elliot USX 31-9, 31-10 Tank Battery	EG

General Comment:

ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 290602 Type: WELL API Number: 123-25148 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 452637 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Well is plugged and abandoned (Elliot 31-10); ECMC form 42 notice of start of plugging operations doc #404307731 received on 08/06/2025. Wellhead OLF has been removed; bellhole excavations observed at flowline pipe removal pull points between WH & facility (backfilled). The facility/ tank battery has been decommissioned; tanks and equipment removed. On location dump and process flowlines at facility/ battery are removed. Remediation work at PA well is in progress.	maclarej	10/03/2025
As outlined on ECMC form 19 spill report Doc #404358639 received on 09/23/2025: While conducting facility decommissioning activities at Extraction's Elliot USX S 31-10 flowline riser, historical impacts were discovered. Lease operators are coached to do routine AVO inspections at all oil and gas facilities.	maclarej	10/03/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300501	PA well area; view E to facility	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7266706
717300502	Flowline (OLF) removal; BH excavation backfilled	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7266707
717300503	Facility decommissioned; OOS GMR view W	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7266708