

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/02/2025

Submitted Date:

10/03/2025

Document Number:

717300504

**FIELD INSPECTION FORM**

Loc ID 311485 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

4 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		ECMCInspections@Oxy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281246	WELL	SI	07/01/2022	GW	123-23367	TEGELER 11-30	PA

**General Comment:**

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)  
[Photos uploaded](#)

**Inspected Facilities**

Facility ID: 281246 Type: WELL API Number: 123-23367 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
As outlined on ECMC form 19 spill report Doc #404359804 received on 09/19/2025: While conducting wellhead plugging and abandonment and flowline removal activities at the Tegeler 11-30 wellhead, historically impacted soil was discovered at the wellhead. The volume of the release is unknown. The wellhead has been plugged and abandoned.	maclarej	10/03/2025
Well is plugged and abandoned (Tegeler 11-30); ECMC form 42 notice of start of plugging operations doc #403960110 received on 10/16/2024. Wellhead flowline (OL) has been removed; dump and process flowlines removed. ECMC form 42 notice of flowline abandonment completed doc #404334171 received 08/25/2025 The facility/ tank battery is decommissioned; tanks and equipment removed. No flowlines/ risers observed at PA well or facility/ battery areas. Remediation work is in progress.	maclarej	10/03/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300505	Excavation at PA well; No FL/ risers	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7267195">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7267195</a>
717300506	Excavation at facility/ battery; OOS GMR	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7267196">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7267196</a>