

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC HMU 10-1D (A10W) Pad

Location #: 334924



Photo # 4238 From entrance to location



Photo # 4239 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC HMU 10-1D (A10W) Pad

Location #: 334924




Photo # 4240 Location



Photo # 4241 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC HMU 10-1D (A10W) Pad

Location #: 334924



Photo # 4242 Location



Photo # 4243 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC HMU 10-1D (A10W) Pad

Location #: 334924



Photo # 4244 Unused flowline lacks lockout tagout (OOSLAT)

Photo # 4245 Unused flowline lacks lockout tagout (OOSLAT)

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC HMU 10-1D (A10W) Pad

Location #: 334924



Photo # 4246 Unused flowline lacks lockout tagout (OOSLAT)



Photo # 4247 Unused flowline lacks lockout tagout (OOSLAT)

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC HMU 10-1D (A10W) Pad

Location #: 334924



Photo # 4248 Unmarked deadman



Photo # 4249 Same unmarked deadman

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC HMU 10-1D (A10W) Pad

Location #: 334924



Photo # 4250 Same unmarked deadman



Photo # 4251 Cattle panel laying on ground