

# Inspection Photos

09/24/2025

**Operator:** TEP Rocky Mountain LLC #96850

**Location ID:** 324099

**Inspection Doc:** 719200274

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324099



**Photo 1:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324099



**Photo 2:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324099



**Photo 3:** Photos showing that secondary containment at methanol tanks at the location are not covered and do not possess adequate wildlife egress. Comply with Rule 902.b.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324099



**Photo 4:** Photos showing erosion, rilling and sediment transportation is occurring near stormwater controls on the western portion of the location. Stormwater BMPs appear to be missing or insufficient. Comply with Rule 1002.f. and implement or maintain stormwater BMPs.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324099



**Photo 5:** Photos showing examples of sediment traps on the western portion of the location. Sediment traps are used by cattle; rilling and erosion is occurring in some places. Comply with 1002.f. and maintain stormwater BMPs.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324099



**Photo 6:** Photo showing an example of vehicle tracking occurring on the working pad surface. Gravel is sparse in some areas on the pad. Maintenance is required. Comply with Rule 1002.f. and implement or maintain stormwater BMP's.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 324099



**Photo 7:** Photos showing the eastern interim area. Interim areas are composed of smooth brome and curlycup gumweed with trace amounts of rubber rabbitbrush and big sagebrush. Interim areas are used by cattle. Interim areas are progressing towards 1003 reclamation requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources