

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/07/2025

Submitted Date:

10/07/2025

Document Number:

719700174

FIELD INSPECTION FORM

Loc ID 310465 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292990	WELL	TA	05/26/2020	GW	123-26439	LETTERLY-USX AB 23-13	TA

General Comment:

*This is an audit of the scout card and related documents followed by an AMA. (Alternate Method Audit).

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	<p>Prior audit: CORRECTIVE ACTION Item(s): Overgrown vegetation at wellsite(s). Refer to Rule 606.c for guidance. *Remove, manage, & control overgrown vegetation around wellsite(s). Comply with Rule 606.c. (30-days). CA Date: 10/27/2025.</p> <p>This audit: *CORRECTIVE ACTION Item(s) RESOLUTION Comment: FIR Resolution Form FIRR doc. #404372775 asserts: 1.) Overgrown vegetation around wellsite has been mitigated as of 09/29/2025. Operator provided photo for verification. See photo(s) #1, 2.</p>		
Corrective Action:			Date:

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 292990 Type: WELL API Number: 123-26439 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Prod valves shut.
Locked-Out, Tagged-Out | LOTO.
OOSLAT applied at wellsite.
ECMC records last prod: 03/2017.

Defined Inactive: 02/28/2015.
Form 6A on file. Out-of-Svc Designation.
Date: 01/01/2015. Approved.
Form 4 on file. Temporarily Abandoned | TA.
Date: 11/28/2018.
Form 6N on file. Notice of intent to Abandon.
Date: 03/28/2025.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/04/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Audit Report Synopsis:</p> <p>On TUE 10/07/2025 at approximately 09:15 hrs. I, Bret Evins, conducted an AMA: Alternate Method Audit at: Operator Name: NOBLE ENERGY INC Location Name: LETTERLY-USX AB67N64W/23SWSW Location ID: 310465 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>Audit observations: Well(s): 1: Temporarily Abandoned TA. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.553305 / -104.525849</p> <p>* While conducting this audit, the following prior possible compliance issues appear to be addressed: *CORRECTIVE ACTION Item(s) RESOLUTION Comment: Refer to pg 2, "Good Housekeeping" section of this report.</p> <p>*FIR Resolution Form FIRR doc. #404372775 asserts: 1.) Overgrown vegetation around wellsite has been mitigated as of 09/29/2025. Operator provided photo for verification. See photo(s) #1, 2.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	10/07/2025
<p>This is a WELL inspection. (AMA: Alternate Method Audit). Well(s): 1: Shut-In SI. Battery: Abandoned. ALL equipment has been removed. Abandoned Battery SE corner GPS coordinates: 40.553305 / -104.525849</p> <p>*Follow-up to Field Audit Report doc. #719700128 dated 09/24/2025. *Follow-up to FIR Resolution Form (FIRR) doc. #404372775 dated 09/29/2025.</p>	evinsb	10/07/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700175	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7270340