

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2025

Submitted Date:

09/28/2025

Document Number:

719700138

FIELD INSPECTION FORM

Loc ID 305806 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 13 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282467	WELL	SI	11/01/2023	OW	123-23507	PAPPENHEIM 22-24	SI

General Comment:

**This is an audit of the scout card and related documents followed by a field audit.*

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	OOSLAT applied at separator. *Refer to Emergency Contact Number section below.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	CORRECTIVE ACTION ITEM(s): During this inspection the following possible compliance issue(s) were observed: 1.) Emergency contact number with Comapny & Well Name NOT posted at wellsite. Refer to Rule 605.d for guidance.		
Corrective Action:	*Post emergency contact number with Comapny & Well Name at wellsite. Comply with Rule 605.d. (30-days). See photo(s) #1.	Date:	10/29/2025
Good Housekeeping:			
Type	WEEDS		
Comment:	CORRECTIVE ACTION ITEM(s): During this inspection the following possible compliance issue(s) were observed: 2.) Overgrown vegetation at wellsite(s). Refer to Rule 606.c for guidance.		
Corrective Action:	*Remove, manage, & control overgrown vegetation around wellsite(s). Comply with Rule 606.c. (30 days) See photo(s) #1.	Date:	10/29/2025
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	
Equipment:			
Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.561164,-104.505511
Comment:	Centralized Battery serves 3 Location IDs (305806, 305807, 305808). (Well(s): 3: Shut-In SI). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 282467 Type: WELL API Number: 123-23507 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Shut-In | SI.
 Prod valves shut.
 Locked-Out, Tagged-Out | LOTO.
 OOSLAT applied at separator.
 ECMC records last prod: 10/2023.

 Form 5B on file. Defined Inactive: 10/31/2023. Approved.
 Flowline shared w/ Pappenheim 32-24.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/07/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Audit Report Synopsis:</p> <p>On WED 09/24/2025 at approximately 16:43 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: PDC ENERGY INC Location Name: PAPPENHEIM-67N64W/24SEW Location ID: 305806 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Mostly Sunny, wet from prior storm.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>*CORRECTIVE ACTION ITEM(s): 2 1.) Refer to pg 2, "Signs/Marker" section of this report. 2.) Refer to pg 2, "Good Housekeeping" section of this report.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	09/28/2025

<p>This is a WELL audit. Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 3 Location IDs (305806, 305807, 305808). (Well(s): 3: Shut-In SI).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference (Associated Well(s), Battery / Facility Audits): A.) Field Audit Report doc. #719700136 and/or Location ID #305808 for SI Well(s) info. B.) Field Audit Report doc. #719700138 and/or Location ID #305806 for SI Well(s) info. C.) Field Audit Report doc. #719700140 and/or Location ID #305807 for SI Well(s) info. D.) Field Audit Report doc. #719700142 and/or Location ID #305808 for Battery / Facility, Equipment info.</p>	<p>evinsb</p>	<p>09/28/2025</p>
---	---------------	-------------------

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404371051	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7257712
719700139	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7257709