

TEP
 Scott 24B
 Location ID: 335079



Location

Location

TEP
Scott 24B
Location ID: 335079



Location



Location

TEP
Scott 24B
Location ID: 335079



ECD is not running and not metered



Location

TEP
Scott 24B
Location ID: 335079



Location

Tank label is illegible

TEP
Scott 24B
Location ID: 335079



Tank liner has multiple areas with holes



Tank liner has multiple areas with holes

TEP
Scott 24B
Location ID: 335079



Tank liner has multiple areas with holes, weeds are growing through liner.



Tank liner has multiple areas with holes