

WELL NAME: RUTABAGA 23-11, API #: 071-09003, INSP. # 716301583



EVERGREEN
NATURAL RESOURCES LLC

RUTABAGA 23-11

API No. 05-071-09003

NE SW SECTION 11-32S-68W

COC60203A CR 42

LAT. 37.27203/LONG. -104.96922

EMERGENCY No. 911 or 719-846-7898 (24 Hrs)

WDID 1911722 / Permit 173411

Network: Oct 8, 2025 at 12:41:11 PM MDT
Local: Oct 8, 2025 at 12:41:11 PM MDT
+37.272271,-104.969377
Las Animas County
Altitude:2572.7meter
Speed:0.0km/h

PHOTO 1: WELL SIGN



PHOTO 2: LOCATION.



PHOTO 3: DEBREE FROM SOUND WALLS. REMOVE DEBREE PER RULE 606. CA DATE 11-8-2025.



Network: Oct 8, 2025 at 12:42:23 PM MDT
Local: Oct 8, 2025 at 12:42:23 PM MDT
+37.272110,-104.969087
Las Animas Count
Altitude:2573.6mete
Speed:1.0km/h

PHOTO 4: UNUSED EQUIPMENT (SOUND WALLS IN DESREPAIR AND NOT IN USE). REPAIR OR REMOVE SOUND WALLS PER RULE 606. CA DATE 11-8-2025.



Network: Oct 8, 2025 at 12:44:25 PM MDT
Local: Oct 8, 2025 at 12:44:25 PM MDT
+37.271988,-104.969205
Las Animas County
Altitude:2574.7meter
Speed:1.7km/h

PHOTO 5: UNUSED EQUIPMENT (APPEARS TO BE A LAND OWNER CAMP TRAILER STORED ON LOCATION). REMOVE UNUSED EQUIPMENT PER RULE 606. IF THIS IS A LAND OWNERS EQUIPMENT OPERATOR WILL NEED TO FILE FOR A VARIANCE. CA DATE 11-8-2025.



Network: Oct 8, 2025 at 12:42:35 PM MDT
Local: Oct 8, 2025 at 12:42:35 PM MDT
+37.272110,-104.969087
Las Animas County
Altitude:2572.6meter
Speed:0.2km/h

PHOTO 6: UNUSED EQUIPMENT (1" RISER NOT IN USE AND NOT MARKED). REMOVE OR MARK UNUSED EQUIPMENT PER RULE 606. CA DATE 11-8-2025.

Calibration Report

Report Date	8/20/24 9:24 AM	Collection Time	8/20/24 9:22 AM
Section 1 - Meter		System	Contact # 719-846-7898
Device ID	104109003	Field	Raton Basin
Location	Rutabaga 23-11	State	Colorado
		Producer	Evergreen Natural Resources
		Purchaser	Colorado Interstate Gas

Section 2 - Setup		Tap Type	Flange	Specific Gravity	0.56
Current Plate Size	0.375	SP Tap Location	Up Stream		
Pipe Size	1.94	Temperature Bias	0		
Atmos. Pressure	10.95	Temperature Base	60		
Pressure Base	14.73				

	Yes	No		Yes	No		Yes	No
Plate Inspected?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Dirty	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Nicked?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Edges Sharp?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Plate Mic'd	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Warped?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Seal Ring Damaged?	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Pitted	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Bevel Downstream	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Section 3 - Meter Tube Inspection		Yes	No	Yes	No
Tube Inspected?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Nicked?	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Dirty?	<input type="checkbox"/>	<input checked="" type="checkbox"/>			
Pitted?	<input type="checkbox"/>	<input checked="" type="checkbox"/>			

Network: Oct 8, 2025 at 12:46:18 PM MDT
 Local: Oct 8, 2025 at 12:46:18 PM MDT
 +37.272311,-104.969361
 Las Animas County
 Altitude:2572.1meter
 Speed:0.4km/h

DIFFERENTIAL				STATIC PRESSURE				TEMP	
FOUND		LEFT		FOUND		LEFT		FOUND	
Test	Meter	Test	Meter	Test	Meter	Test	Meter	Test	Meter

PHOTO 7: ANNUAL GAS METER CALIBRATION PAST DUE. Calibrate gas metering equipment annually to comply with rule 430.d.(1). CA DATE 11-8-2025.