

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC KRK 7-6 (C7E) Pad

Location #: 334560




Photo # 3956 From entrance to location

Photo # 3957 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC KRK 7-6 (C7E) Pad

Location #: 334560



Photo # 3958 Location



Photo # 3959 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC KRK 7-6 (C7E) Pad

Location #: 334560



Photo # 3960 Location

Photo # 3961 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC KRK 7-6 (C7E) Pad

Location #: 334560




Photo # 3962 Location



Photo # 3963 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC KRK 7-6 (C7E) Pad

Location #: 334560



Photo # 3964 Location



Photo # 3965 Signs at separators have previous operators name

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC KRK 7-6 (C7E) Pad

Location #: 334560



Photo # 3966 Sign at separator has previous operators name

Photo # 3967 Sign at separator has previous operators name

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC KRK 7-6 (C7E) Pad

Location #: 334560



Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC KRK 7-6 (C7E) Pad

Location #: 334560



Photo # 3970 Sign at separator has previous operators name



Photo # 3971 Pneumatic control valve on summit pipeline has been modified/valve no longer has the ability to close

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC KRK 7-6 (C7E) Pad

Location #: 334560



Photo # 3972 Pneumatic control valve on summit pipeline has been modified/valve no longer has the ability to close