

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/30/2025

Submitted Date:

10/03/2025

Document Number:

715203012

FIELD INSPECTION FORM

Loc ID 303631 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Findings:

- 10 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat		pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253401	WELL	PR	01/03/1991	GW	125-07278	EKBERG 3-33	PR

General Comment:

This is a field audit of the scout card, related documents and the location conducted by SE Compliance Specialist Brian Welsh

Location

Lease Road:

Type	Access		
comment:	Gravel road through pasture		
Corrective Action:			Date:

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Lease sign at location is missing		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 10/30/2025

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	Wire panels around unit and wellhead		
Corrective Action:			Date:

Equipment:

Type	#		corrective date
Ancillary equipment	# 1		
Comment:	Gas scrubber		
Corrective Action:			Date:
Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:			Date:
Prime Mover	# 1		
Comment:	Kohler gas engine		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		39.839000,-102.185300
Comment:	Central tank battery for Ekberg 3-33 and 4-33 2450' SE of wellhead				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity) 210bbbs	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 253401 Type: WELL API Number: 125-07278 Status: PR Insp. Status: PR

Producing Well

Comment: Producing. Casing production. Central meter run for (Ekberg 1-33, 3-33, 4-33, Renzelman 21-33, 32-33 and 42-33) 1800' WSW @ 39.84273/-102.19473. Production reports are up to date at time of inspection

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404379295	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7266930
715203070	pumping unit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7266925