

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CRYSTAL CREEK MV 3-30

Location ID: 322532



Photo # 6021 From entrance to location



Photo # 6022 Location

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CRYSTAL CREEK MV 3-30

Location ID: 322532



Photo # 6023 Location



Photo # 6024 Location

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CRYSTAL CREEK MV 3-30

Location ID: 322532



Photo # 6025 Location




Photo # 6026 Location

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CRYSTAL CREEK MV 3-30

Location ID: 322532



Photo # 6027 Location



Photo # 6028 Open ended load line

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CRYSTAL CREEK MV 3-30

Location ID: 322532



Photo # 6029 Open ended load line



Photo # 6030 Open ended load line

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CRYSTAL CREEK MV 3-30

Location ID: 322532



Photo # 6031 Open ended load line



Photo # 6032 Open ended load line

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CRYSTAL CREEK MV 3-30

Location ID: 322532



**Photo # 6033 Burner exhaust stack on tank heater lacks bird protection/available for entry by wildlife/wildlife hazard**



**Photo # 6034 Burner exhaust stack on tank heater lacks bird protection/available for entry by wildlife/wildlife hazard**

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CRYSTAL CREEK MV 3-30

Location ID: 322532



**Photo # 6035 Open ended pipe on production tank/available for entry by wildlife/wildlife hazard**



**Photo # 6036 Open ended pipe on production tank/available for entry by wildlife/wildlife hazard**

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CRYSTAL CREEK MV 3-30

Location ID: 322532



Photo # 6037 Unmarked deadman



Photo # 6038 Same unmarked deadman

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CRYSTAL CREEK MV 3-30

Location ID: 322532



Photo # 6039 Same unmarked deadman



Photo # 6040 Unmarked deadman

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CRYSTAL CREEK MV 3-30

Location ID: 322532



Photo # 6041 Fencing around tank battery needs maintenance



Photo # 6042 Fencing around tank battery needs maintenance

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CRYSTAL CREEK MV 3-30

Location ID: 322532



Photo # 6043 Fencing around tank battery needs maintenance



Photo # 6044 Fencing around tank battery needs maintenance