

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/13/2025

Submitted Date:

10/13/2025

Document Number:

697011960

**FIELD INSPECTION FORM**

Loc ID 302174 Inspector Name: Peterson, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10459  
Name of Operator: EXTRACTION OIL & GAS INC  
Address: 555 17TH STREET SUITE 3700  
City: DENVER State: CO Zip: 80202

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                         | Comment |
|--------------|-------|-------------------------------|---------|
|              |       | Inspections@civiresources.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 286934      | WELL | SI     | 08/01/2025  | GW         | 123-27294 | PERKINS 29-44 | SI          |

**General Comment:**

[This is a field audit of the scout card, related documents and the location.](#)

**Location**

Overall Good:

**Signs/Marker:**

|                    |               |       |  |
|--------------------|---------------|-------|--|
|                    | Type WELLHEAD |       |  |
| Comment:           |               |       |  |
| Corrective Action: |               | Date: |  |

**Emergency Contact Number:**

|                    |                      |       |                      |
|--------------------|----------------------|-------|----------------------|
| Comment:           | <input type="text"/> |       |                      |
| Corrective Action: | <input type="text"/> | Date: | <input type="text"/> |

**Good Housekeeping:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | WEEDS  |       |            |
| Comment:           | Weeds were observed around the wellhead, see attaced photos. |       |            |
| Corrective Action: | Comply with Rule 606   | Date: | 10/31/2025 |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |               |       |  |
|--------------------|---------------|-------|--|
|                    | Type WELLHEAD |       |  |
| Comment:           | Panel         |       |  |
| Corrective Action: |               | Date: |  |

**Equipment:**

|                    | #                                      | Type  | corrective date |
|--------------------|--|-------|-----------------|
| Type: Flow Line    | # 1                                    |       |                 |
| Comment:           |  |       |                 |
| Corrective Action: |  | Date: |                 |
| Type: Bradenhead   | # 1                                    |       |                 |
| Comment:           | Bradenhead valve is exposed at surface |       |                 |
| Corrective Action: |  | Date: |                 |
| Type: Plunger Lift | # 1                                    |       |                 |
| Comment:           |  |       |                 |
| Corrective Action: |  | Date: |                 |

**Tanks and Berms:**

| Contents           | #                | Capacity | Type                | Tank ID | SE GPS |
|--------------------|------------------|----------|---------------------|---------|--------|
|                    |                  |          | CENTRALIZED BATTERY |         |        |
| Comment:           | Location #306199 |          |                     |         |        |
| Corrective Action: |                  |          |                     | Date:   |        |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

| Yes/No             | NO |       |  |
|--------------------|----|-------|--|
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 286934 Type: WELL API Number: 123-27294 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

| Comment   | User      | Date       |
|---|-----------|------------|
| <p><b>ECMC Audit Report Summary</b><br/>                     On Monday 10/13/2025 at approximately 12:40 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Extraction Perkins 29-44 location #302174 in Weld County, Colorado.<br/>                     While there, I observed weeds around the wellhead. During this inspection the following possible compliance issues were observed: Rule 606. with a corrective action date of 10/31/2025. A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.<br/>                     This is a summary of the inspection report.</p> | petersont | 10/13/2025 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 697011961    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7278556">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7278556</a> |