

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/10/2025

Submitted Date:

10/13/2025

Document Number:

719700180

FIELD INSPECTION FORM

Loc ID 419026 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

14 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
482763	TANK BATTERY	AC	08/18/2022		-	Smith PC AB 18-03 Tank Battery	AO

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action:			Date:	
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	BATTERY			
Comment:				
Corrective Action:			Date:	
Type	CONTAINERS			
Comment:	Battery site: Propane, Nitrogen; Placards.			
Corrective Action:			Date:	
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	Posted.			
Corrective Action:			Date:	_____
Good Housekeeping:				
Type				
Comment:				
Corrective Action:			Date:	
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	SEPARATOR			
Comment:	Surrounded by earth berms.			
Corrective Action:			Date:	
Equipment:				
Type: Bird Protectors	# 4			corrective date
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			

	Comment: Gas Sales, Master; (Phillips 66). Calibration card(s) indicates calibration <= 1 year. Last calibration: 07/08/2025.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	Battery site: 1: Nitrogen tank(s) for Instrument Air. 2: ECD scrubber(s). 1: Propane tank(s).		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:	1: Crude oil storage vapor line combustor(s). Controls crude oil storage vapors. Pilots: ON. 1: Separator vapor line combustor(s). Controls separator vapors. Pilots: ON.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 1 Location ID (419036). (Well(s): 1: Producing PR). Centralized Battery serves 1 Tank Battery Facility ID (482763).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

Paint	
Condition	
Other (Content)	
Other (Capacity)	60 Bbls.
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Berms shared w/ crude oil tank(s), produced H2O vault(s).				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.579803,-104.595215
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Berms shared w/ crude oil tank(s), produced H2O vault(s).				
Corrective Action:				Date:

Wells Served By Facilities Above	AirsID
API Number	API Number AirsID
123-32115	

Venting:	Yes/No	NO		
Comment:				
Corrective Action:				Date:

Flaring:	Type	
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 482763 Type: TANK API Number: - Status: AC Insp. Status: AO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Audit Report Synopsis:</p> <p>On FRI 10/10/2025 at approximately 11:12 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: NOBLE ENERGY INC Facility Name: Smith PC AB 18-03 Tank Battery/ Facility ID: 482763 Location Name: SMITH PC AB/18-03 Location ID: 419036 Well Name(s): See photo(s) #6 attached to this report. API: See "Wells Served By Facilities Above" sec on pg. 4 and/or photo(s) #6 attached to this report. Location County: Weld County, Colorado Weather: Mostly Cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Producing PR. Battery: Active.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	10/13/2025
<p>This is a BATTERY audit. Well(s): 1: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 1 Location ID (419036). (Well(s): 1: Producing PR).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (482763).</p> <p>Reference (Associated Well(s), Battery Audits): A.) Field Inspection Report doc. #719700178 and/or Location ID #419036 for PR Well(s) info. B.) Field Inspection Report doc. #719700180 and/or Facility ID #482763 for Battery / Facility, Equipment info.</p>	evinsb	10/13/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700181	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7279123