

Final Reclamation Inspection

September 12, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 331556

Inspection Document #: 718800855

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GADDIS #41-36
Location ID: 331556



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards as corn growth did not match that of reference areas.



Photo 2. Photo taken of well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: GADDIS #41-36
Location ID: 331556



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: GADDIS #41-36
Location ID: 331556



Photo 5. Photo taken of the well location, facing south. Photo illustrates that final reclamation activities have taken place, but weedy annual vegetation including kochia (*Bassia scoparia*) was observed at the location and corn growth did not match that of reference areas.



Photo 6. Photo taken of the reference area to the well location, west of the location, facing east. Photo illustrates alfalfa and corn cropland.



Inspection Photos
Location Name: GADDIS #41-36
Location ID: 331556



Photo 7. Photo taken of the tank battery location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. Weed annual vegetation including kochia (*Bassia scoparia*) was observed across the location.



Photo 8. Photo taken of the tank battery location, facing southeast. Photo illustrates midstream equipment remains at the location.

Inspection Photos
Location Name: GADDIS #41-36
Location ID: 331556



Photo 9. Photo taken of the tank battery location, facing west. See comments under Photo 7.



Photo 10. Photo taken of the tank battery location, facing south. See comments under Photo 7.

Inspection Photos
Location Name: GADDIS #41-36
Location ID: 331556



Photo 11. Photo taken ground cover at the tank battery location, facing north. Photo illustrates weedy annual vegetation including kochia (*Bassia scoparia*).



Photo 12. Photo taken of the reference area to the well location, south of the location, facing southeast. Photo illustrates alfalfa cropland bordering a wetland area with weedy annual vegetation.

