

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/10/2025

Submitted Date:

10/13/2025

Document Number:

699507586

FIELD INSPECTION FORM

Loc ID 322159 Inspector Name: MEDINA, JUSTIN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 74165
Name of Operator: RENEGADE OIL & GAS COMPANY LLC
Address: 6155 S MAIN STREET #225
City: AURORA State: CO Zip: 80016

Findings:

- 6 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Blakeman, Audrey		audrey.blakeman@state.co.us	
Silver, Randy		randy.silver@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
Burn, Diana		diana.burn@state.co.us	
Waggoner, Kyle		kyle.waggoner@state.co.us	
Ahmadian, Alexander		alexander.ahmadian@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
, Renegade		ed@renegadeoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209389	WELL	SI	01/01/2018	OW	039-06293	WHITEHEAD 12-16	SI

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment: Temporary pit is full, some leaking on sides of berm, stormwater issues may arise if stormwater overflows temporary pit.

Corrective Action: Comply with rule 1002.f.(2)B

Date: 10/13/2025

Good Housekeeping:

Type OTHER

Comment: Temporary pit is full, some leaking on sides of berm, stormwater issues may arise if stormwater overflows temporary pit

Corrective Action: Comply with rule 1002.f.(2)B

Date: 10/13/2025

Type UNUSED EQUIPMENT

Comment: Unused equipment on loation needs to be removed.

Corrective Action: Comply with rule 606

Date: 05/29/2025

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date: <u> </u>

Flaring:

Type		
Comment:		
Corrective Action:		Date: <u> </u>

Inspected Facilities

Facility ID: 209389 Type: WELL API Number: 039-06293 Status: SI Insp. Status: SI

Workover

Comment: At time of audit temporary pit was discovered on location used to store drilling/wellbore fluids. At time of audit no rig presonnel were on location.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: FLOWBACK

Estimated Spill Volume: 20

Comment: Renegade has used a temporary bermed pit to store drilling/well fluids on side. Site has also been excavated from wellhead to where the pit is located. No notification from Renegade for any well work recently. Form 42 MIRU, was filed on 5/28/25. No other forms have been filed for this well, unable to determine what type of downhole work that is being performed. Wolf creek is approx 300 ' from well location.

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 10/13/2025

Reportable: YES

GPS: Lat 39.536827

Long -104.387492

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On 10/10/2025 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Whitehead 12-16 Company Name- Renegade API- 05-039-06293 In Elbert County Colorado. While there, I observed Workover Rig.</p> <p>Drone Deploy walkthrough is available at:</p> <p>https://www.dronedeploy.com/app2/sites/68e97cb3ad5b5557aa8c8673/maps/68ed2fefe50fbb077371baae/pano-viewer/68ed2fefe50fbb077371baae This is a follow up inspection from document # 699507175Corrective Actions are Delinquent</p> <p>During this inspection the following possible compliance issues were observed: Unused equipment. Rule 606. 5/29/25 Spill. Rule 912 a. 10/13/25 Stormwater. Rule 1002 f (2). 10/13/25 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p>	medinaj	10/13/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699507587	Audit Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7279365