

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/10/2025

Submitted Date:

10/14/2025

Document Number:

719700184

FIELD INSPECTION FORM

Loc ID 306734 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

15 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
306734	LOCATION	AC			-	DILLARD-67N64W 4SENW	IO

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Barbed wire. Surrounded by metal berms.		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Barbed wire.		
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:	Barbed wire.		
Corrective Action:			Date:

Equipment:					corrective date
Type: Emission Control Device	# 1				
Comment:	1: Crude oil storage vapor line combustor(s). Controls crude oil storage vapors. Pilots: OFF. Shut-down.				
Corrective Action:					Date:
Type: Horizontal Heated Separator	# 1				
Comment:					

Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter removed from meter run.		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	Centralized Battery serves 1 Location ID (306734). (Well(s): 1: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.601560,-104.554020
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms shared w/ crude oil, produced H2O tank(s), produced H2O vault(s).			

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLs	CONCRETE SUMP/VAULT			
Comment:						
Corrective Action:					Date:	

Paint

Condition						
Other (Content)						
Other (Capacity)	48 Bbls.					
Other (Type)						

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: Berms shared w/ crude oil tank(s), produced H2O vault(s).						
Corrective Action:					Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	PBV FIBERGLASS			
Comment:						
Corrective Action:					Date:	

Paint

Condition						
Other (Content)						
Other (Capacity)	75 Bbls.					
Other (Type)						

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: Berms shared w/ crude oil tank(s), produced H2O vault(s).						
Corrective Action:					Date:	

Wells Served By Facilities Above

API Number
123-25171

AirsID


API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:



Inspected Facilities

Facility ID: 306734 Type: LOCATION API Number: - Status: AC Insp. Status: IO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Audit Report Synopsis:</p> <p>On FRI 10/10/2025 at approximately 12:36 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: NOBLE ENERGY INC Facility Name: Pending Facility ID: Pending Location Name: DILLARD-67N64W/4SEW Location ID: 306734 Well Name(s): See photo(s) #8 attached to this report. API: See "Wells Served By Facilities Above" sec on pg. 4 and/or photo(s) #8 attached to this report. Location County: Weld County, Colorado Weather: Mostly Cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	10/14/2025
<p>This is a BATTERY audit. Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 1 Location ID (306734). (Well(s): 1: Temporarily Abandoned TA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference (Associated Well(s), Battery Audits): A.) Field Inspection Report doc. #719700182 and/or Location ID #306734 for TA Well(s) info. B.) Field Inspection Report doc. #719700184 and/or Location ID #306734 for Battery / Facility, Equipment info.</p>	evinsb	10/14/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700185	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7280445