

FORM  
INSPRev  
X/20

# State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/25/2025

Submitted Date:

10/08/2025

Document Number:

707801830

## FIELD INSPECTION FORM

Loc ID 335153	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 15 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> ECMC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: 1058 COUNTY ROAD 215 City: PARACHUTE State: CO Zip: 81635				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261190	WELL	PR	12/27/2007	GW	045-07929	SCOTT 2-36	PR
279978	WELL	PR	09/13/2005	GW	045-11126	SCOTT 31A-36-692	PR
279979	WELL	PR	02/11/2006	GW	045-11127	SCOTT 21B-36-692	PR
279980	WELL	PR	02/03/2006	GW	045-11128	SCOTT 21D-36-692	PR
279982	WELL	PR	02/03/2006	GW	045-11125	SCOTT 31C-36-692	PR
281345	WELL	PR	08/06/2006	GW	045-11434	SCOTT 22D-36-692	PR
281346	WELL	PR	08/02/2006	GW	045-11435	SCOTT 32C-36-692	PR
281347	WELL	PR	08/05/2006	GW	045-11436	SCOTT 22B-36-692	PR

**General Comment:**

CECMC Inspection Report Summary  
 On Wednesday 9/25/2025, I, Inspector Scott Ramsey, conducted a routine inspection/audit at TEP Scott 2-36, at Location # 335153 in Garfield County Colorado.  
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.  
 While there, I observed normal production operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad. No evidence of a tracking pad on location.

During this inspection the following compliance issues were observed:  
 1. Random debris.  
 2. Tank sign is illegible.  
 Refer to photographs of observed compliance issues.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank sign is illegible.		
Corrective Action:	Provide proper labeling	Date:	11/14/2025

<b>Emergency Contact Number:</b>			
Comment:	911/970-285-9377		
Corrective Action:		Date:	

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Random debris.		
Corrective Action:	Remove debris	Date:	10/17/2025

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 17		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	Not running and not metered		
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 8		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	200 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	10	200 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

**Venting:**

--

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	261190	Type:	WELL	API Number:	045-07929	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	279978	Type:	WELL	API Number:	045-11126	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	279979	Type:	WELL	API Number:	045-11127	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	279980	Type:	WELL	API Number:	045-11128	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	279982	Type:	WELL	API Number:	045-11125	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	281345	Type:	WELL	API Number:	045-11434	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	281346	Type:	WELL	API Number:	045-11435	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	281347	Type:	WELL	API Number:	045-11436	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

**Producing Well**

Comment: Producing

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Maintenance relative to storm water runoff, operators shall consider seasonal factors, such as winter snow cover and spring runoff from snowmelt, to ensure site and access road conditions and controls are adequate and in place to effectively manage storm water.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404383979	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7272382">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7272382</a>
707801834	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7272372">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7272372</a>