

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/08/2025

Submitted Date:

10/08/2025

Document Number:

716301583

FIELD INSPECTION FORM

Loc ID 309034 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1775 SHERMAN ST. #2775
City: DENVER State: CO Zip: 80203

Findings:

- 11 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	Insp. w/ca's

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286986	WELL	PR	04/15/2007	CBM	071-09003	RUTABAGA 23-11	PR

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	PHOTO 3: DEBREE FROM SOUND WALLS.		
Corrective Action:	REMOVE DEBREE PER RULE 606.	Date:	11/08/2025
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 6: UNUSED EQUIPMENT (1" RISER NOT IN USE AND NOT MARKED).		
Corrective Action:	REMOVE OR MARK UNUSED EQUIPMENT PER RULE 606. CA DATE 11-8-2025.	Date:	11/08/2025
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 5: UNUSED EQUIPMENT (APPEARS TO BE A LAND OWNER CAMP TRAILER STORED ON LOCATION).		
Corrective Action:	REMOVE UNUSED EQUIPMENT PER RULE 606. IF THIS IS A LAND OWNERS EQUIPMENT OPERATOR WILL NEED TO FILE FOR A VARIANCE.	Date:	11/08/2025
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 4: UNUSED EQUIPMENT (SOUND WALLS IN DESREPAIR AND NOT IN USE).		
Corrective Action:	REPAIR OR REMOVE SOUND WALLS PER RULE 606. CA DATE 11-8-2025.	Date:	11/08/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Gas Meter Run	# 1		
Comment:	PHOTO 7: ANNUAL GAS METER CALIBRATION PAST DUE.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	11/08/2025
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	

Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 286986 Type: WELL API Number: 071-09003 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/19/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: YES Pit ID: 301230 Lat: 37.272010 Long: -104.968700

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: Adequate

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: YES Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Tuesday 10-8-2025 at approximately 12:40, I Tom Beardslee Conducted an on-site inspection an Evergreen Natural Resources location RUTABAGA 23-11 API# 05-071-09003 in Las Animas County Colorado. While there, I observed production operation. During this inspection the following possible compliance issues were observed: PHOTO 3: DEBREE FROM SOUND WALLS. REMOVE DEBREE PER RULE 606. CA DATE 11-8-2025. PHOTO 4: UNUSED EQUIPMENT (SOUND WALLS IN DESREPAIR AND NOT IN USE). REPAIR OR REMOVE SOUND WALLS PER RULE 606. CA DATE 11-8-2025. PHOTO 5: UNUSED EQUIPMENT (APPEARS TO BE A LAND OWNER CAMP TRAILER STORED ON LOCATION). REMOVE UNUSED EQUIPMENT PER RULE 606. IF THIS IS A LAND OWNERS EQUIPMENT OPERATOR WILL NEED TO FILE FOR A VARIANCE. CA DATE 11-8-2025. PHOTO 6: UNUSED EQUIPMENT (1" RISER NOT IN USE AND NOT MARKED). REMOVE OR MARK UNUSED EQUIPMENT PER RULE 606. CA DATE 11-8-2025. PHOTO 7: ANNUAL GAS METER CALIBRATION PAST DUE. Calibrate gas metering equipment annually to comply with rule 430.d.(1). CA DATE 11-8-2025. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	10/08/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404384783	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7273020
716301584	INSP PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7273016