

Inspection Photos  
Location Name: Rice 06-06 J I  
Location ID: 305815



Wellhead



Disconnected flowline