

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/15/2025

Submitted Date:

10/15/2025

Document Number:

719700213

FIELD INSPECTION FORM

Loc ID 306145 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
306145	LOCATION	AC			-	R. MILLER-67N64W 24NWSW	IO

General Comment:

*This is an audit of the scout card and related documents followed by an AMA. (Alternate Method Audit).

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Prior audit: CORRECTIVE ACTION Item(s): Overgrown vegetation at Battery site. Refer to Rule 606.c for guidance. *Remove, manage, & control overgrown vegetation around Battery site. Comply with Rule 606.c. (30-days). CA Date: 10/27/2025. This audit: *CORRECTIVE ACTION Item(s) RESOLUTION Comment: FIR Resolution Form FIRR doc. #404372780 asserts: 1.) Overgrown vegetation around Battery site has been mitigated as of 09/29/2025. Operator provided photo for verification. See photo(s) #4, 5, 6, 7.		
Corrective Action:			Date:

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

AirsID

API Number
123-24058

API Number	AirsID

123-24057

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 306145 Type: LOCATION API Number: - Status: AC Insp. Status: IO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Audit Report Synopsis:</p> <p>On WED 10/15/2025 at approximately 09:15 hrs. I, Bret Evins, conducted an AMA: Alternate Method Audit at: Operator Name: PDC ENERGY INC Facility Name: Pending Facility ID: Pending Location Name: R. MILLER-67N64W/24NWSW Location ID: 306145 Well Name(s): See photo(s) #7 attached to this report. API: See "Wells Served By Facilities Above" sec on pgs. 2-3 and/or photo(s) #10 attached to this report. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>Audit observations: Well(s): 2: Shut-In SI. Battery: Inactive Shut-down.</p> <p>*While conducting this audit, the following prior possible compliance issues appear to be addressed: *CORRECTIVE ACTION Item(s) RESOLUTION Comment: Refer to pg 2, "Good Housekeeping" section of this report.</p> <p>*FIR Resolution Form FIRR doc. #404372780 asserts: 1.) Overgrown vegetation around Battery site has been mitigated as of 09/29/2025. Operator provided photo for verification. See photo(s) #4, 5, 6, 7.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	10/15/2025
<p>This is a BATTERY Audit. (AMA: Alternate Method Audit). Well(s): 2: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (306145, 306146). (Well(s): 2: Shut-In SI).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>*Follow-up to Field Audit Report doc. #719700134 dated 09/24/2025. *Follow-up to FIR Resolution Form (FIRR) doc. #404372780 dated 09/29/2025.</p>	evinsb	10/15/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700214	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7282338