

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/14/2025

Submitted Date:

10/15/2025

Document Number:

717300526

FIELD INSPECTION FORM

Loc ID 413452 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		rbucogccinspectionreports@chevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412462	WELL	SI	10/01/2022	GW	123-30487	STROH H 12-20	PA
427447	LOCATION	AC			-	STROH PC H 12-31D TANK	EG

General Comment:

ECMC Engineering Integrity Inspection; Flowline Inspection
Photos uploaded

Inspected Facilities

Facility ID: 412462 Type: WELL API Number: 123-30487 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 427447 Type: LOCATION API Number: - Status: AC Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Well is plugged and abandoned (Stroh H 12-20); ECMC form 42 notice of MIRU doc #404197717 received on 05/09/2025. The facility/ tank battery has been decommissioned; tanks, equipment and flowlines removed. No flowlines/ risers observed at PA well or facility/ battery areas. Remediation is in progress.	maclarej	10/15/2025
As outlined on COGCC form 19 spill report Doc #404365295 received on 09/24/2025: Historical impacts were discovered during flowline decommissioning activities along the flowline where the area is most likely to be impacted. Due to the historical nature of the release, an exact cause was not able to be identified. Noble conducts routine AVO inspections of all oil and gas flowlines in order to identify and mitigate potential releases. Further, this flowline is no longer active and is in the process of being decommissioned. The flowline has been taken out of service and there is no longer a possibility of a release originating from this infrastructure.	maclarej	10/15/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300537	PA well; view NW to facility (decommissioned)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7282424
717300538	Facility decommissioned; view SE (OOS GMRs)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7282425