

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/16/2025

Submitted Date:

10/16/2025

Document Number:

697011982

**FIELD INSPECTION FORM**

Loc ID 441369 Inspector Name: Peterson, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 18 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email   | Comment |
|--------------|-------|---|---------|
|              |       | rbucogccinspectionreports@chevron.onmicrosoft.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name              | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------------|-------------|
| 441361      | WELL | PR     | 08/01/2019  | OW         | 123-41359 | Chandler Farms HD 20-332HC | SI          |
| 441362      | WELL | PR     | 08/01/2019  | OW         | 123-41360 | Chandler Farms HD 20-212HN | SI          |
| 441363      | WELL | PR     | 09/01/2024  | OW         | 123-41361 | Chandler Farms HD 20-349HN | SI          |
| 441364      | WELL | PR     | 05/01/2017  | OW         | 123-41362 | Chandler Farms HD 20-269HN | SI          |
| 441365      | WELL | PR     | 05/01/2017  | OW         | 123-41363 | Chandler Farms HD 20-389HN | SI          |
| 441366      | WELL | PR     | 11/01/2019  | OW         | 123-41364 | Chandler Farms HD 20-229HC | SI          |
| 441367      | WELL | PR     | 11/01/2019  | OW         | 123-41365 | Chandler Farms HD 20-229HN | SI          |
| 441368      | WELL | PR     | 03/01/2022  | OW         | 123-41366 | Chandler Farms HD 20-332HN | SI          |
| 441370      | WELL | PR     | 08/01/2019  | OW         | 123-41367 | Chandler Farms HD 20-372HC | SI          |
| 441371      | WELL | PR     | 05/01/2017  | OW         | 123-41368 | Chandler Farms HD 20-372HN | SI          |
| 441372      | WELL | PR     | 08/01/2019  | OW         | 123-41369 | Chandler Farms HD 20-252HN | SI          |
| 441382      | WELL | PR     | 08/01/2019  | OW         | 123-41374 | Chandler Farms HD 20-292HN | SI          |
| 441386      | WELL | PR     | 09/01/2018  | OW         | 123-41375 | Chandler Farms HD 20-269HC | SI          |

**General Comment:**

[This is a field audit of the scout card, related documents and the location.](#)

**Location**

Overall Good:

**Signs/Marker:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | CONTAINERS   |       |            |
| Comment:           | Methanol systems   |       |            |
| Corrective Action: |  | Date: |            |
| Type               | TANK LABELS/PLACARDS   |       |            |
| Comment:           | Produced water vault at compressor lacks capacity placard, see attached photo. |       |            |
| Corrective Action: | Install sign to comply with Rule 605.h.  | Date: | 11/17/2025 |
| Type               | WELLHEAD   |       |            |
| Comment:           | x 13   |       |            |
| Corrective Action: |  | Date: |            |
| Type               | BATTERY  |       |            |
| Comment:           |  |       |            |
| Corrective Action: |  | Date: |            |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | WEEDS  |       |            |
| Comment:           | Weeds were observed around compressor soundwalls, see attached photos. |       |            |
| Corrective Action: | Comply with Rule 606.  | Date: | 11/17/2025 |
| Type               | TRASH  |       |            |
| Comment:           | Stainless tubing next to soundwall, see attached photo.                |       |            |
| Corrective Action: | Comply with Rule 606.  | Date: | 11/17/2025 |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |                          |       |  |
|--------------------|--------------------------|-------|--|
| Type               | OTHER                    |       |  |
| Comment:           | Soundwalls at compressor |       |  |
| Corrective Action: |                          | Date: |  |
| Type               | WELLHEAD                 |       |  |
| Comment:           | Panel                    |       |  |
| Corrective Action: |                          | Date: |  |

| Equipment:                        |   | corrective date  |
|-----------------------------------|---|------------------|
| Type: VRT                         | # 2   |                  |
| Comment:                          |   |                  |
| Corrective Action:                |   | Date:            |
| Type: Ancillary equipment         | #   |                  |
| Comment:                          | Bulk oil storage at compressor wildlife protection is inadequate, see attached photo.   |                  |
| Corrective Action:                | Install or repair wildlife protection equipment.  | Date: 11/17/2025 |
| Type: LACT                        | # 1   |                  |
| Comment:                          |   |                  |
| Corrective Action:                |   | Date:            |
| Type: Pig Station                 | # 2   |                  |
| Comment:                          |   |                  |
| Corrective Action:                |   | Date:            |
| Type: Horizontal Heated Separator | # 11  |                  |
| Comment:                          |   |                  |
| Corrective Action:                |   | Date:            |
| Type: Prime Mover                 | # 3   |                  |
| Comment:                          | Natural gas engines on compressor, genset and VRU   |                  |
| Corrective Action:                |   | Date:            |
| Type: Vertical Separator          | # 5   |                  |
| Comment:                          |   |                  |
| Corrective Action:                |   | Date:            |
| Type: Bird Protectors             | # 20  |                  |
| Comment:                          |   |                  |
| Corrective Action:                |   | Date:            |
| Type: Flow Line                   | # 13  |                  |
| Comment:                          |   |                  |
| Corrective Action:                |   | Date:            |
| Type: Plunger Lift                | # 13  |                  |
| Comment:                          |   |                  |
| Corrective Action:                |   | Date:            |
| Type: Gas Meter Run               | # 2   |                  |
| Comment:                          | DCP calibration cards are current.  |                  |
| Corrective Action:                |   | Date:            |
| Type: Ancillary equipment         | #   |                  |
| Comment:                          | Automation array, solar array, ECD scrubbers, methanol systems in secondary containment, bulk lube oil storage in secondary containment with wildlife protection, supplied air system, nitrogen system, recirc pump, genset, electrical systems |                  |
| Corrective Action:                |   | Date:            |
| Type: Gathering Line              | # 1   |                  |
| Comment:                          |   |                  |

|                               |   |       |  |
|-------------------------------|---|-------|--|
| Corrective Action:            |   | Date: |  |
| Type: Prime Mover             | # 2                                       |       |  |
| Comment:                      | Electric motors on LACT and recirc pump   |       |  |
| Corrective Action:            |   | Date: |  |
| Type: Bird Protectors         | # 7                                       |       |  |
| Comment:                      |   |       |  |
| Corrective Action:            |   | Date: |  |
| Type: Compressor              | # 1                                       |       |  |
| Comment:                      |   |       |  |
| Corrective Action:            |   | Date: |  |
| Type: Emission Control Device | # 6                                       |       |  |
| Comment:                      |   |       |  |
| Corrective Action:            |   | Date: |  |
| Type: VRU                     | # 1                                       |       |  |
| Comment:                      |   |       |  |
| Corrective Action:            |   | Date: |  |
| Type: Bradenhead              | # 13                                      |       |  |
| Comment:                      | Bradenhead valves are exposed at surface. |       |  |
| Corrective Action:            |   | Date: |  |

**Tanks and Berms:**

| Contents           | #        | Capacity | Type           | Tank ID | SE GPS |
|--------------------|----------|----------|----------------|---------|--------|
| PRODUCED WATER     | 1        | OTHER    | PBV FIBERGLASS |         | ,      |
| Comment:           | 150 bbls |          |                |         |        |
| Corrective Action: |          |          |                |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type        | Tank ID | SE GPS |
|--------------------|---|----------|-------------|---------|--------|
| PRODUCED WATER     | 1 | <50 BBLs | BV CONCRETE |         | ,      |
| Comment:           |   |          |             |         |        |
| Corrective Action: |   |          |             |         | Date:  |

**Paint**

|           |          |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

|                  |  |
|------------------|--|
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |

|                    |       |
|--------------------|-------|
| Comment:           |       |
| Corrective Action: | Date: |

| Contents       | # | Capacity | Type           | Tank ID | SE GPS |
|----------------|---|----------|----------------|---------|--------|
| PRODUCED WATER | 3 | OTHER    | FIBERGLASS AST |         | ,      |

|                    |       |
|--------------------|-------|
| Comment: 533 bbls  |       |
| Corrective Action: | Date: |

**Paint**

|           |          |  |
|-----------|----------|--|
| Condition | Adequate |  |
|-----------|----------|--|

|                  |  |
|------------------|--|
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |

|                    |       |
|--------------------|-------|
| Comment:           |       |
| Corrective Action: | Date: |

| Contents  | #  | Capacity | Type      | Tank ID | SE GPS |
|-----------|----|----------|-----------|---------|--------|
| CRUDE OIL | 12 | OTHER    | STEEL AST |         | ,      |

|                    |       |
|--------------------|-------|
| Comment: 533 bbls  |       |
| Corrective Action: | Date: |

**Paint**

|           |          |  |
|-----------|----------|--|
| Condition | Adequate |  |
|-----------|----------|--|

|                  |  |
|------------------|--|
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |

|                    |       |
|--------------------|-------|
| Comment:           |       |
| Corrective Action: | Date: |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 441361 Type: WELL API Number: 123-41359 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 441362 Type: WELL API Number: 123-41360 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 441363 Type: WELL API Number: 123-41361 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 441364 Type: WELL API Number: 123-41362 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 441365 Type: WELL API Number: 123-41363 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 441366 Type: WELL API Number: 123-41364 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 441367 Type: WELL API Number: 123-41365 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 441368 Type: WELL API Number: 123-41366 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 441370 Type: WELL API Number: 123-41367 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 441371 Type: WELL API Number: 123-41368 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 441372 Type: WELL API Number: 123-41369 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 441382 Type: WELL API Number: 123-41374 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 441386 Type: WELL API Number: 123-41375 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In       Temporarily Abandoned      Reminder: \_\_\_\_\_

Comment:

Corrective Action:       Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs   | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|-----------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  | Self Inspection | Pass                     |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

| Comment  | User      | Date       |
|--|-----------|------------|
| <p><a href="#">ECMC Audit Report Summary</a><br/>                     On Thursday 10/16/2025 at approximately 09:10 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the PDCE Chandler Farms HD 20-212 HN Pad location #441369 in Weld County, Colorado.<br/>                     While there, I observed trash and weeds on location, inadequate wildlife protections on a bulk lube oil storage tank and missing capacity placard on the compressor vault. During this inspection the following possible compliance issues were observed: Rule 605.h. with a corrective action date of 11/17/2025, Rule 606. with a corrective action date of 11/17/2025, Rule 902.b. with a corrective action date of 11/17/2025. A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.<br/>                     This is a summary of the inspection report.</p> | petersont | 10/16/2025 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 697011983    | Photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7284420">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7284420</a> |