

Inspection Photos

Location Name: Dillard USX AB/09-99HZ

Location #: 415940



Photo #1

Dillard USX AB 09-99HZ, 05-99HZ Battery site

Inactive | Shut-down

Equipment documented: Loc. ID 415940



Photo #2

Dillard USX AB 09-99HZ, 05-99HZ Battery site

Inactive | Shut-down

Wellsite(s), Battery entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Dillard USX AB/09-99HZ

Location #: 415940



Photo #3

Dillard USX AB 09-99HZ, 05-99HZ Battery site

Inactive | Shut-down

Crude Oil tank(s), Produced H2O vault(s); SE corner



Photo #4

Dillard USX AB 09-99HZ, 05-99HZ Battery site

Inactive | Shut-down

Separator(s), ECD(s)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Dillard USX AB/09-99HZ

Location #: 415940



Photo #5

Dillard USX AB 09-99HZ, 05-99HZ Battery site

Inactive | Shut-down

Battery signage



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: Dillard USX AB/09-99HZ

Location #: 415940

Associated Well(s)	API	Location	Status
1. Dillard USX AB 09-99HZ	123-31237	415940	TA
2. Dillard USX AB 05-99HZ	123-31254	415930	SI

Photo #6

Dillard USX AB 09-99HZ, 05-99HZ Battery site

Inactive | Shut-down

Associated well(s)

1: Shut-In | SI; 1: Temporarily Abandoned | TA



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources