

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/16/2025

Submitted Date:

10/18/2025

Document Number:

719700215

**FIELD INSPECTION FORM**

Loc ID 415940 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

13 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416035	WELL	TA	02/28/2022	OW	123-31237	DILLARD USX AB 09-99HZ	TA

**General Comment:**

\*This is an audit of the scout card and related documents followed by a field audit.

Location						
<b>Lease Road:</b>						
Type	Access					
comment:	Adequate					
Corrective Action					Date:	
Overall Good: <input type="checkbox"/>						
<b>Signs/Marker:</b>						
Type	WELLHEAD					
Comment:	Blue TA tag at well. OOSLAT at separator(s).					
Corrective Action:					Date:	
Emergency Contact Number:						
Comment:	Posted.					
Corrective Action:					Date:	
<b>Good Housekeeping:</b>						
Type	WEEDS					
Comment:	Comment Only: Overgrown vegetation at wellsite(s). Clear, remove, manage overgrown vegetation at wellsite(s). See photo(s): #1.					
Corrective Action:					Date:	
Overall Good: <input type="checkbox"/>						
<b>Spills:</b>						
Type	Area	Volume				
In Containment: No						
Comment:						
<input type="checkbox"/> Multiple Spills and Releases?						
<b>Fencing/:</b>						
Type	WELLHEAD					
Comment:	Iron panel, barbed wire.					
Corrective Action:					Date:	
<b>Equipment:</b>						
					corrective date	
Type: Other	# 1					
Comment:	Wellhead: w/ Master, casing valves.					
Corrective Action:					Date:	
Type: Bradenhead	# 1					
Comment:	Appears plumbed to surface.					
Corrective Action:					Date:	
<b>Tanks and Berms:</b>						
Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.593903,-104.563392	

Comment:	Centralized Battery serves 2 Location IDs (415940, 415930). (Well(s): 1: Temporarily Abandoned   TA; 1: Shut-In   SI). Centralized Battery serves 1 Tank Battery Facility ID (Pending).		
Corrective Action:		Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 416035 Type: WELL API Number: 123-31237 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.  
Disconnected from flowline.  
Locked-Out, Tagged-Out | LOTO.  
Blue TA tag posted.  
OOSLAT applied at separator(s).  
ECMC records last production: 02/2020.  
  
Form 4 on file. TA Date: 02/08/2022.  
Defined Inactive: 02/29/2020.  
Form 6A on file. Out-of-Svc Designation.  
Date: 02/15/2020. Approved.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 04/16/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments
---------------

Comment	User	Date
<p><b>CECMC Audit Report Synopsis:</b></p> <p>On THU 10/16/2025 at approximately 16:05 hrs. I, Bret Evins, conducted an onsite audit at:                      Operator Name: NOBLE ENERGY INC                      Location Name: Dillard USX AB/09-99HZ                      Location ID: 415940                      Well Name(s) &amp; API:                      Reference:                      See "Inspected Facilities" section on page 1 of this report.                      Location County: Weld County, Colorado                      Weather: Mostly Sunny, dry.</p> <p>While there, I observed:                      Well(s): 1: Temporarily Abandoned   TA.                      Battery: Inactive   Shut-down.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	10/18/2025
<p>This is a WELL Audit.                      Well(s): 1: Temporarily Abandoned   TA.                      Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (415940, 415930).                      (Well(s): 1: Temporarily Abandoned   TA; 1: Shut-In   SI).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference (Associated Well(s), Battery Audits):                      A.) Field Inspection Report doc. #719700215 and/or Location ID #415940 for TA Well(s) info.                      B.) Field Inspection Report doc. #719700217 and/or Location ID #415930 for SI Well(s) info.                      C.) Field Inspection Report doc. #719700219 and/or Location ID #415940 for Battery / Facility, Equipment info.</p>	evinsb	10/18/2025

<b>Attached Documents</b>		
You can go to ECMC Images ( <a href="https://ecmc.state.co.us/weblink/">https://ecmc.state.co.us/weblink/</a> ) and search by document number:		
Document Num	Description	URL
719700216	Audit photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7287284">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7287284</a>