

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/17/2025

Submitted Date:

10/20/2025

Document Number:

719700221

**FIELD INSPECTION FORM**

Loc ID 418974 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418969	WELL	PR	02/01/2025	OW	123-32080	Waugh PC AB08-13	PR

**General Comment:**

\*This is an audit of the scout card and related documents followed by a field audit.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted.		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	CORRECTIVE ACTION Item(s): 1.) Stained soil at wellsite(s). Refer to Rules 905.e (Oily Waste) & 608.e (Mechanical Conditions) for guidance. * All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition. All equipment will be engineered, operated, and maintained within the manufacturer's recommended specifications.		
Corrective Action:	** Mitigate stained soil around wellsite(s). Comply with Rules 905.e (Oily Waste) & 608.e (Mechanical Conditions). (30-days). See photo(s) #1.		Date: <u>11/19/2025</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Iron pipe.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Prime Mover	# 1		corrective date
Comment:	Gas engine drives pump jack. Surrounded by protective shed.		
Corrective Action:			Date:
Type: Pump Jack	# 1		

Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.581838,-104.580730
Comment:	Centralized Battery serves 1 Location ID (418974). (Well(s): 1: Producing   PR). Centralized Battery serves 1 Tank Battery Facility ID (481876).				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 418969 Type: WELL API Number: 123-32080 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing | PR.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 03/29/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>This is a WELL audit. Well(s): 1: Producing   PR. Battery: Active.</p> <p>Centralized Battery serves 1 Location ID (418974). (Well(s): 1: Producing   PR).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (481876).</p> <p>Reference (Associated Well(s), Battery Audits): A.) Field Inspection Report doc. #719700221 and/or Location ID #418974 for PR Well(s) info. B.) Field Inspection Report doc. #719700223 and/or Facility ID #481876 for Battery / Facility, Equipment info.</p>	evinsb	10/20/2025
<p>CECMC Audit Report Synopsis:</p> <p>On FRI 10/17/2025 at approximately 13:56 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: NOBLE ENERGY INC Location Name: Waugh PC/AB08-13 Location ID: 418974 Well Name(s) &amp; API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Mostly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Producing   PR. Battery: Active.</p> <p>*CORRECTIVE ACTION Item(s): 1.) See "Good Housekeeping" section on page 2 of this report.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	10/20/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700222	Audit photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7288975">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7288975</a>