

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/21/2025

Submitted Date:

10/21/2025

Document Number:

714202599

FIELD INSPECTION FORM

Loc ID 318246 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240951	WELL	PR	08/01/2019	GW	123-08739	LANSONS FARM 16	PR

General Comment:

[THIS IS AN AUDIT IN RESPONSE TO A COMPLAINT.](#)

Inspected Facilities

Facility ID: 240951 Type: WELL API Number: 123-08739 Status: PR Insp. Status: PR

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Brittani Santistevan
 Complaint Received
 Date: 10/16/25
 Complaint Contacted: No
 Date: Time:
 Location ID #: 318246
 Inspection Document #: 714202596
 Complaint Inspection Doc: 714202599
 Complaint Document #: 200451726
 Nature of Complaint: odor
 Field Inspector Actions:
 On October 16, 2025, I Brittani Santistevan, area field inspector, was assigned a complaint received by ECMC staff in reference to Odor. The complainant stated an odor was occurring outside of complainants home. I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, I did discover some emissions released from the pumpjack near the casing using soapy water and FLIR video to identify where the leak was. At the time of inspection, I spoke with KPK and they sent someone out to location to possibly mitigate the issue.
 Weather conditions: sunny, dry ground
 A violation of ECMC rules was observed at the time of the inspection.
 All information reviewed and site inspection information were submitted to the ECME for further review.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12