

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/20/2025

Submitted Date:

10/21/2025

Document Number:

720800086

**FIELD INSPECTION FORM**

Loc ID 317527 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10673  
Name of Operator: GADECO LLC  
Address: 7535 EAST HAMPDEN AVE STE 400  
City: DENVER State: CO Zip: 80231

**Findings:**

- 13 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Jenkins, Steve		steve.jenkins@state.co.us	
Green, Trent		trent@gfccap.com	
Pagano, Theodore	(970) 590-3944	tapagano@helena-resources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239188	WELL	TA	12/07/2022	OW	123-06129	GRAEFE 1	PR

**General Comment:**

[This is a Well and Production Facility Field Compliance Audit of the Scout Card, Related Documents and the Location.](#)

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	<a href="#">Tanks are missing NFPA, Content and Capacity Labels</a>		
Corrective Action:	<a href="#">Install sign to comply with Rule 605.h.</a>		Date: <u>11/04/2025</u>
Type	WELLHEAD		
Comment:	<a href="#">Adequate</a>		
Corrective Action:			Date:
Type	BATTERY		
Comment:	<a href="#">Adequate</a>		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	<a href="#">Adequate</a>		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<a href="#">Missing 24 Hour Emergency Contact Number on Wellhead and Tank Battery Signs; see photos</a>		
Corrective Action:	<a href="#">Install sign to comply with Rule 605</a>		Date: <u>11/04/2025</u>
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	<a href="#">dead weeds/vegetation around Pumping Unit and Tank berm; see photos</a>		
Corrective Action:	<a href="#">Comply with Rule 606 and 1003.f</a>		Date: <u>11/04/2025</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: <u>No</u>			
Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
			corrective date
Type: Bradenhead	# 1		
Comment:	<a href="#">Appears to be plumbed to surface</a>		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	<a href="#">Electric Motor drive Pumping Unit</a>		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		

Comment:		
Corrective Action:		Date:
Type: Other	# 1	
Comment:	Propane Tank (500 Gallons)	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:					
					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	750 BBLS
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		40.721230,-104.295276
Comment:					
Corrective Action:					
					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	750 BBLS
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	
	Date:

**Flaring:**

Type	
------	--

Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 239188 Type: WELL API Number: 123-06129 Status: TA Insp. Status: PR

**Producing Well**

Comment: [PR - Well Producing at the time of this Field Audit. Form 4 Sundry - 404361906 dated 09.26.2025](#)

Corrective Action:		Date:	
--------------------	--	-------	--

**BradenHead**

Date of Last Brhd Test: 02/14/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: [Bradenhead Annual Test not current Form 17 - 403323691 dated 02.16.2023 with a Test Date of 02.14.2023](#)

11/04/2025

Corrective Action: <a href="#">Preform Bradenhead Test and submit Form 17 per Rule 419.c</a>	Date:
--	-------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
720800087	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7290426">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7290426</a>