

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/21/2025

Submitted Date:

10/21/2025

Document Number:

720800088

**FIELD INSPECTION FORM**

Loc ID 331872 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10673  
Name of Operator: GADECO LLC  
Address: 7535 EAST HAMPDEN AVE STE 400  
City: DENVER State: CO Zip: 80231

**Findings:**

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Jenkins, Steve		steve.jenkins@state.co.us	
Green, Trent		trent@gfccap.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267624	WELL	TA	10/19/2022	DSPW	123-21426	CROISSANT 1	TA

**General Comment:**

[This is a Well Site Field Compliance Audit of the Scout Card, Related Documents and the Location.](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:			
Corrective Action:		Date:	

**Good Housekeeping:**

Type	WEEDS		
Comment:	Overgrown vegetation around Wellsite; see photos		
Corrective Action:	Comply with Rule 606 and 1003.f	Date:	11/04/2025

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

				corrective date
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:		Date:		
Type: Other	# 1			
Comment:	TA Wellhead			
Corrective Action:		Date:		
Type: Bradenhead	# 1			
Comment:	Appears to be plumbed to surface			
Corrective Action:		Date:		

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 267624 Type: WELL API Number: 123-21426 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: TA - Last MIT 02.14.2023

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 02/14/2023 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Bradenhead Annual Test not current. Form 17 403323652 dated 02.16.2023 with a Test Date of 02.14.2023 11/04/2025

Corrective Action: Complete Annual Bradenhead Test and submit Form 17 per Rule 419.c Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
720800089	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7290427">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7290427</a>