

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/20/2025

Submitted Date:

10/21/2025

Document Number:

715203212

**FIELD INSPECTION FORM**

Loc ID 311103 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 305 S RIDGE STREET #6279  
City: BRECKENRIDGE State: CO Zip: 80424

**Findings:**

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                        | Comment |
|--------------|-------|------------------------------|---------|
| Dolezal, Pat |       | pat.dolezal@ownresources.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 298835      | WELL | PR     | 02/01/2011  | GW         | 125-11496 | MASSIVE 19-9  | PR          |

**General Comment:**

[This is a field audit of the scout card, related documents and the location conducted by SE Compliance Specialist Brian Welsh](#)

**Location**

|                    |                           |       |  |
|--------------------|---------------------------|-------|--|
| <b>Lease Road:</b> |                           |       |  |
| Type               | Access                    |       |  |
| comment:           | Dirt road through pasture |       |  |
| Corrective Action: |                           | Date: |  |

Overall Good:

|                      |   |       |            |
|----------------------|---|-------|------------|
| <b>Signs/Marker:</b> |   |       |            |
| Type                 | WELLHEAD  |       |            |
| Comment:             | Lease sign by metal shed. Lease sign is not legible |       |            |
| Corrective Action:   | Install sign to comply with Rule 605.d.             | Date: | 11/20/2025 |

|                                  |   |  |             |
|----------------------------------|---|--|-------------|
| <b>Emergency Contact Number:</b> |   |  |             |
| Comment:                         | <input style="width: 100%;" type="text"/> |  |             |
| Corrective Action:               | <input style="width: 100%;" type="text"/> |  | Date: _____ |

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Fencing/:</b>   |  |       |  |
| Type               | WELLHEAD   |       |  |
| Comment:           | Metal panels around wellhead, metal shed and VGS |       |  |
| Corrective Action: |  | Date: |  |

|                           |   |       |                 |
|---------------------------|---|-------|-----------------|
| <b>Equipment:</b>         |   |       | corrective date |
| Type: Vertical Separator  | # 2   |       |                 |
| Comment:                  | 1-Vertical gas separator 50% buried by metal shed<br>1-Vertical gas separator in metal shed |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Ancillary equipment | # 1   |       |                 |
| Comment:                  | Telemerty equipment   |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Gas Meter Run       | # 1   |       |                 |
| Comment:                  | Meter run in metal shed   |       |                 |
| Corrective Action:        |   | Date: |                 |

|                    |   |       |  |
|--------------------|---|-------|--|
| <b>Venting:</b>    |   |       |  |
| Yes/No             |   |       |  |
| Comment:           | <input style="width: 100%;" type="text"/> |       |  |
| Corrective Action: |   | Date: |  |

|                 |  |  |  |
|-----------------|--|--|--|
| <b>Flaring:</b> |  |  |  |
| Type            |  |  |  |

|                    |       |  |
|--------------------|-------|--|
| Comment:           |       |  |
| Corrective Action: | Date: |  |

**Inspected Facilities**

Facility ID: 298835 Type: WELL API Number: 125-11496 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description    | URL   |
|--------------|----------------|---|
| 715203226    | location photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7290754">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7290754</a> |