

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/17/2025

Submitted Date:

10/21/2025

Document Number:

719700225

**FIELD INSPECTION FORM**

Loc ID 415787 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

13 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415811	WELL	PR	12/01/2024	OW	123-31184	KOHLHOFF USX AB 17-04P	SI

**General Comment:**

\*This is an audit of the scout card and related documents followed by a field audit.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	Posted.		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Iron rod.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Iron panel, barbed wire.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:	Inactive. Shut-down. Brake applied.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Gas engine drives pump jack. Surrounded by protective shed. Inactive. Shut-down.		
Corrective Action:			Date:

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.577988,-104.574596
Comment:	Centralized Battery serves 1 Location ID (415787). (Well(s): 1: Shut-In   SI). Centralized Battery serves 1 Tank Battery Facility ID (481877).				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			
			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	
	Date:

**Inspected Facilities**

Facility ID: 415811 Type: WELL API Number: 123-31184 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Shut-In | SI.  
Observed prod valves shut.  
Pump jack brake applied.  
Locked-Out, Tagged-Out | LOTO at separator.  
Functional tag applied at separator.

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/13/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:   
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><b>CECMC Audit Report Synopsis:</b></p> <p>On FRI 10/17/2025 at approximately 12:53 hrs. I, Bret Evins, conducted an onsite audit at:                      Operator Name: NOBLE ENERGY INC                      Location Name: KOHLHOFF USX AB/17-04P                      Location ID: 415787                      Well Name(s) &amp; API:                      Reference:                      See "Inspected Facilities" section on page 1 of this report.                      Location County: Weld County, Colorado                      Weather: Mostly Sunny, dry.</p> <p>While there, I observed:                      Well(s): 1:Shut-In   SI.                      Battery: Inactive   Shut-down.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	10/21/2025

<p>This is a WELL inspection. Well(s): 1: Shut-In   SI. Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 1 Location ID (415787). (Well(s): 1: Shut-In   SI).</p> <p>Centralized Battery formerly served 3 Location IDs (415738, 415752, 415756). (Well(s): 3: Plugged &amp; Abandoned   PA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (481877).</p> <p>Reference (Associated Well(s), Battery Audits): A.) Field Audit Report doc. #719700225 and/or Location ID #415787 for SI Well(s) info. B.) Field Audit Report doc. #719700227 and/or Location ID #415738 for PA Well(s) info. C.) Field Audit Report doc. #719700229 and/or Location ID #415752 for PA Well(s) info. D.) Field Audit Report doc. #719700231 and/or Location ID #415756 for PA Well(s) info. E.) Field Audit Report doc. #719700233 and/or Facility ID #481877 for Battery / Facility, Equipment info.</p>	<p>evinsb</p>	<p>10/21/2025</p>
--	---------------	-------------------

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700226	Audit photo(s)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7290893">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7290893</a>