

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/21/2025

Submitted Date:

10/22/2025

Document Number:

719000749

FIELD INSPECTION FORM

Loc ID: 325972 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 13 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215660	WELL	PR	02/01/2018	CBM	067-07265	DAVIES A 1	PR

General Comment:

[Inspection Report Summary](#)
On 10/21/25 I Inspector Charles Garcia conducted an on-site inspection.
Location: DAVIES A1
Operator: Simcoe LLC
API#: 067-07265
County: LaPlata

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTERANCE HAS BP AMERICA NOT SIMCOE LLC		
Corrective Action:	INSTALL CORRECT SIGNAGE PER RULE 605	Date:	10/28/2025
Type	TANK LABELS/PLACARDS		
Comment:	PRODUCED WATER TANK		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Contact # 970-247-6916 Emergency #911		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	CATTLE PANELS		
Corrective Action:		Date:	
Type	OTHER		
Comment:	PRODUCED WATER TANK CATTLE PANELS		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	CATTLE PANELS		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	ELECTRIC		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		

Comment:	CHEMICAL CONTAINER WITH SPILL PREVENTION HAS NO LABEL		Date:	10/28/2025
Corrective Action:	INSTALL CORRECT SIGNAGE PER RULE 605			
Type:	Ancillary equipment	# 3		
Comment:	ELECTRIC PANELS TELEMETRY EQUIPMENT		Date:	
Corrective Action:				
Type:	Vertical Heated Separator	# 1		
Comment:			Date:	
Corrective Action:				
Type:	Gas Meter Run	# 1		
Comment:			Date:	
Corrective Action:				
Type:	Deadman # & Marked	# 4		
Comment:			Date:	
Corrective Action:				
Type:	Other	# 1		
Comment:	WELLHEAD		Date:	
Corrective Action:				
Type:	Flow Line	# 1		
Comment:			Date:	
Corrective Action:				

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.108600,-107.000000
Comment:	21 BBL PRODUCED WATER TANK				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000750	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7292913