

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/22/2025

Submitted Date:

10/22/2025

Document Number:

719000758

FIELD INSPECTION FORM

Loc ID 333718 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Findings:

- 11 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258905	WELL	PR	01/04/2001	CBM	067-08389	MCCULLOCH 34-10 27-3	PR
295108	WELL	SI	08/01/2025	CBM	067-09515	SO UTE FC 34-10 27-7	SI

General Comment:

Inspection Report Summary
On 10/22/25 I Inspector Charles Garcia conducted an on-site inspection.
Location: MCCULLOCH 34-10 27-3 SO UTE FC 34-10
API# 067-08389 API# 067-09515
Operator: HILLCORP ENERGY COMPANY
County: LaPlata

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	LOCATION SIGN AT WELLHEAD		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	PRODUCED WATER TANK LABLE NOT LEGIBLE NEEDS REPLACED SEE LOCATION PICTURES		
Corrective Action:	Install sign or correct sign per rule 605	Date:	10/29/2025

Emergency Contact Number:

Comment:	24 Hr #970-247-6916 Emergency #911	Date:	
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	SEPARATOR		
Comment:	HOG WIRE		
Corrective Action:		Date:	

Equipment:

Type	Quantity	Comment	Corrective Action	Date	corrective date
Type: Flow Line	# 2				
Comment:					
Corrective Action:				Date:	
Type: Other	# 2				
Comment:		METER HOUSES CALIBRATION IN COMPLIANCE			
Corrective Action:				Date:	
Type: Pump Jack	# 2				
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	# 2				
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	# 2				
Comment:					
Corrective Action:				Date:	

Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	2 TELEMETRY EQUIPMENT 2 LUBE OIL CONTAINER WITH SPILL PREVENTION FOR PRIME MOVER		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:	GAS		
Corrective Action:			Date:
Type: Other	# 2		
Comment:	WELLHEADS		
Corrective Action:			Date:
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	OTHER		37.158100,-107.925700
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 258905 Type: WELL API Number: 067-08389 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/02/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 295108 Type: WELL API Number: 067-09515 Status: SI Insp. Status: SI

BradenHead

Date of Last Brhd Test: 05/07/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

