

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/10/2025

Submitted Date:

10/16/2025

Document Number:

717900320

**FIELD INSPECTION FORM**

Loc ID 482939 Inspector Name: Robinson, Taylor On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@oxy.com	
,		ECMCInspections@Oxy.com	<a href="#">All Inspections</a>

**General Comment:**

This is an environmental inspection for Location ID 482939 Lomax tank battery. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>					
Type					
Comment:	<input type="text" value="Orange construction fencing is present surrounding two open excavations. Fencing appears to be functional."/>				
Corrective Action:				Date:	

<b>Equipment:</b>				corrective date
Type:	#			
Comment:	<input type="text" value="NO equipment on location."/>			
Corrective Action:				Date:

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Location Construction**

Location ID: 482939 CDP: \_\_\_\_\_

**Comment:** This site has been recently decommissioned and there is no equipment on site. Two open excavations on site, one appears to have exposed groundwater.

**Corrective Action:**  **Date:** \_\_\_\_\_

**Form 2A COAs:**

**Comment:**

**Corrective Action:**  **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:**

**Corrective Action:**  **Date:** \_\_\_\_\_

**Comment:** Large rills appearing at edges of the excavations. Operator to fill, regrade, or install necessary stormwater BMPs.

**Corrective Action:** Install BMPs in accordance with 1002.f.(2) to prevent runoff and runoff. **Date:** 10/30/2025

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: No spills or releases observed during the inspection. Site does have an open remediation project. Rem# 40009.

Corrective Action:  Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404394747	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7284563">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7284563</a>
717900321	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7284555">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7284555</a>