


## Inspection Photos

Location: HORN SPRINGS GAS COM 3-32-33, 1-32

Location ID: 307268

API # 05-071-06101



**Photo 1 – Adjacent well site Information**

**Photo 2 – Location Overview**

## Inspection Photos

Location: HORN SPRINGS GAS COM 3-32-33, 1-32

Location ID: 307268

API # 05-071-06101



**Photo 3 – Impacted soils at arrow and between Dehydration Units**

**Photo 4 – Erosion**

## Inspection Photos

Location: HORN SPRINGS GAS COM 3-32-33, 1-32

Location ID: 307268

API # 05-071-06101



**Photo 5 – Erosion and Noxious Weeds**



**Photo 6 – Noxious weeds**

## Inspection Photos

Location: HORN SPRINGS GAS COM 3-32-33, 1-32

Location ID: 307268

API # 05-071-06101



**Photo 7 – Missing cap, wildlife protection**

**Photo 8 – Dehydration Filters Improperly Stored**

# Inspection Photos

Location: HORN SPRINGS GAS COM 3-32-33, 1-32

Location ID: 307268

API # 05-071-06101



**Photo 9 – Erosion**

**Photo 10 – Erosion**

## Inspection Photos

Location: HORN SPRINGS GAS COM 3-32-33, 1-32

Location ID: 307268

API # 05-071-06101



**Photo 11 – Impacted soils**



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources