

WELL NAME: HORN SPRINGS GAS COM 3-32-33, API #: 071-06101, INSP. # 716301577




PHOTO 1: WELL SIGN



Network: Oct 1, 2025 at 9:56:49 AM MDT
Local: Oct 1, 2025 at 9:56:48 AM MDT
+37.217390,-104.780668
Las Animas County
Altitude:2283.7meter
Speed:0.0km/h

PHOTO 2: LOCATION.



PHOTO 3: AROW SHOWING THE EQUIPMENT WITH THE FAILURE APP. 120' TO THE NORTH OF THE EDGE OF LOCATION, THERE IS A ROW BETWEEN THE METHANOL TANK AND THE DEHYDRATOR EQUIPMENT THAT IS NOT SHOWN IN PHOTO.



Network: Oct 1, 2025 at 9:39:12 AM MDT
Local: Oct 1, 2025 at 9:39:12 AM MDT
+37.217708,-104.780619
Las Animas County
Altitude:2282.1meter
Speed:0.0km/h


PHOTO 4: IMAGE SHOWING THE SPILL AREA. THE BULK OF THE SPILL FLUID IS APP. 35' AROUND THE EQUIPMENT WITH SOME SPRAY REACHING OUT TO THE EAST AND SOUTH APP. 50'.



PHOTO 5: ANOTHER IMAGE SHOWING THE SPILL AREA. THE BULK OF THE SPILL FLUID IS APP. 35' AROUND THE EQUIPMENT WITH SOME SPRAY REACHING OUT TO THE EAST AND SOUTH APP. 50'.



PHOTO 6: ANOTHER IMAGE SHOWING THE SPILL AREA. THE BULK OF THE SPILL FLUID IS APP. 35' AROUND THE EQUIPMENT WITH SOME SPRAY REACHING OUT TO THE EAST AND SOUTH APP. 50'.



Network: Oct 1, 2025 at 9:40:37 AM MDT
Local: Oct 1, 2025 at 9:40:37 AM MDT
+37.217780,-104.780933
Las Animas County
Altitude:2279.8meter
Speed:1.9km/h

PHOTO 7: CLOSER IMAGE OF THE EQUIPMENT WITH THE MECHANICAL FAILURE. OPERATOR INFORMED ECMC STAFF THAT THE FILTER MARKED BY THE ARROW PLUGGED AND CAUSED THE FAILURE.