

FORM INSP Rev X/20	State of Colorado Energy and Carbon Management Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>10/23/2025</u> Submitted Date: <u>10/23/2025</u> Document Number: <u>719000769</u>
FIELD INSPECTION FORM			

Loc ID 334057 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 56680
 Name of Operator: MERRION OIL & GAS CORP
 Address: 610 REILLY AVENUE
 City: FARMINGTON State: NM Zip: 87401

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Thompson, Philana	(505) 324-5300	pthompson@merrion.bz	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284872	WELL	PR	11/01/2020	CBM	067-09173	ANTARES 1	PR
292046	WELL	PR	12/01/2020	CBM	067-09388	SHAULA 1	PR

General Comment:

Inspection Report Summary
 On 10/23/25 | Inspector Charles Garcia conducted an on-site inspection.
 Location: ANTARES #1, SHAULA #1
 Operator: MERRION OIL & GAS CORP
 API#: 067-09173 API#067-09388
 County: LaPlata

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	LOCATION SIGNS		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	PRODUCED WATER TANK LABEL NOT LEGIBLE		
Corrective Action:	Install sign or correct sign per rule 605	Date:	10/30/2025
Emergency Contact Number:			
Comment:	505-324-5300 911 EMERGENCY		
Corrective Action:		Date:	
Good Housekeeping:			
Type	WEEDS		
Comment:	OVERGROWN VEGATATION ON LOCATION DRY TUMBLE WEEDS ALL ALONG CATTLE PANELS AND FENCE LINE SEE LOCATION PICTURES		
Corrective Action:	Control weeds and undesirable vegetation per Rule 606". Keep areas around wellheads, tanks and separators clear of weeds (potentially combustible material) per Rule 610.k		Date: 10/07/2025
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	CATTLE PANELS		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	CATTLE PANELS		
Corrective Action:		Date:	
Equipment:			
Type: Bird Protectors # 2			corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment # 2			
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	

Type: Plunger Lift	# 2		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	CALIBRATION IN COMPLIANCE		
Corrective Action:			Date:
Type: Other	# 2		
Comment:	WELLHEADS		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.092300,-107.578200
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 284872 Type: WELL API Number: 067-09173 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 11/04/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 292046 Type: WELL API Number: 067-09388 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 11/04/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719000770	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7294468