

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/16/2025

Submitted Date:

10/17/2025

Document Number:

715203181

FIELD INSPECTION FORM

Loc ID 488949 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10791
Name of Operator: WAVETECH HELIUM INC
Address: 1801 BROADWAY SUITE 600
City: DENVER State: CO Zip: 80202

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Jobe, Patrick	(303) 534-3383	pjobe@wavetechenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
489761	WELL	DG	10/10/2025		017-07828	1 Wavetech Howard 22-29	DG

General Comment:

SE Compliance Specialist Brian Welsh conducted a Drilling Inspection

Location

Lease Road:			
Type	Access		
comment:	Trail through pasture		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	No lease sign at location		
Corrective Action:	Install lease sign	Date:	10/23/2025
Type	DRILLING/RECOMP		
Comment:	Rig number sign at county road. Install rig sign showing rig company		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	At the time of inspection, there was a truck and trailer parked outside of the fenced location. Keep vehicles and equipment inside the fenced area.		
Corrective Action:		Date:	
Type	DEBRIS		
Comment:	Some trash was on the north side of location and blowing off. Keep trash in the trash bin, especially on the windy days		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	LOCATION		
Comment:	Wire fence around entire location		
Corrective Action:		Date:	

Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	500 BBLs	LVST		38.895600,-102.138100	
Comment:	Frac tank on northeast corner of location for water storage					
Corrective Action:						Date:

Paint	
Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	3	500 BBLs	LVST		38.895000,-102.138400
Comment: 3 Frac tanks on east side of rig for water usage					
Corrective Action:				Date:	

Paint	
Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:	
Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 489761 Type: WELL API Number: 017-07828 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: Quest 211 Pusher/Rig Manager: _____
Permit Posted: SATISFACTORY Access Sign: SATISFACTORY

Well Control Equipment:

Pipe Ram: NO Blind Ram: NO Hydril Type: YES
Pressure Test BOP: Pass Test Pressure PSI: _____ Safety Plan: YES

Drill Fluids

Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
Multi-Well: _____ Disposal Location: Onsite

Comment: Rig was in the process of reaming the whole to clean out. Bit depth was 5374' and TD was achieved

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Other	Pass	Covering Materials	Pass	

Comment: [Access is grassed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404395603	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7285739
715203182	location of drilling rig	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7285733
715203183	SE corner of frac tanks next to shaker	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7285734
715203184	Frac tank in NE corner	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7285735