

# Inspection Photos

10/17/2025

**Operator:** TEP Rocky Mountain LLC #96850

**Location ID:** 335069

**Inspection Doc:** 719200339

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335069

10/17/2025 13:06  
238° SW



10/17/2025 13:30  
17° N



10/17/2025 13:07  
70° E



**Photo 1:** Photos showing an overview of the location looking southwest and east (left top and bottom, respectively) and the production equipment shared with location #335175 looking north (top right).



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335069



**Photo 2:** Photos showing an overview of the northeastern and northwestern interim areas, respectively. Northern interim areas are not progressing towards 1003 reclamation requirements; areas are predominantly bare with prickly Russian thistle present. Additional reclamation efforts are required.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335069



**Photo 3:** Photos showing an overview of the southern interim area. The interim area is not progressing towards 1003 reclamation requirements; areas are predominantly bare with prickly Russian thistle present. Additional reclamation efforts are required.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335069



**Photo 4:** Photos showing an overview of the western interim area. Intermediate wheatgrass has established. This portions of the location is progressing towards 1003 reclamation requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335069



**Photo 5:** Photos showing an example of stormwater controls on the northern edge of the working pad surface. The drainage channel appears to be laden with sediment, reducing capacity. Comply with 1002.f.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335069



**Photo 6:** Photos showing an example of a stormwater control on the southwestern edge of the interim area. Stormwater controls appear to be missing or insufficient; check dams are in disrepair, sediment transport is evident, and the stormwater control appears to have reduced capacity, resulting in standing water in the interim area. Comply with 1002.f.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335069



**Photo 7:** Photos showing ponded water on the access road where gravel appears to be sparse. Comply with 1002.f.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources