

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/23/2025

Submitted Date:

10/24/2025

Document Number:

717300554

FIELD INSPECTION FORM

Loc ID 305222 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ECMCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275773	WELL	TA	05/04/2021	OW	123-22671	SWEETGRASS 12-14	PA
327334	LOCATION	CL			-	SWEETGRASS-USX UU-61N68W 14NWNW	EG

General Comment:

[ECMC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities

Facility ID: 275773 Type: WELL API Number: 123-22671 Status: TA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 327334 Type: LOCATION API Number: - Status: CL Insp. Status: EG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
1105. ABANDONMENT 1105.b. Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser.	maclarej	10/24/2025
Well is PA (Sweetgrass 12-14); ECMC form 42 notice of start of plugging operations doc #404233735 received on 06/09/2025. Off location flowline AIP in progress; flowline riser at PA well is bullplugged/ valved. Flowline riser at HHS is disconnected, isolated/ bull plugged. Battery decommissioning is ongoing. Remediation work is in progress.	maclarej	10/24/2025
As outlined on ECMC form 19 spill report Doc #404398795 received on 10/22/2025: While conducting wellhead plugging and abandonment activities at the Sweetgrass 12-14 wellhead, historically impacted soil was discovered at the wellhead. The volume of the release is unknown. The wellhead has been plugged and abandoned.	maclarej	10/24/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717300563	Excavation at PA well; Signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7296532
717300564	Flowline disconnected at HHS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7296533