

Final Reclamation and Stormwater Inspection

October 20, 2025

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 336442

Well Name: MURATA #23-19

Inspection Document #: 718601080

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MURATA #23-19
Location ID: 336442



Photo 1. Looking southeast down the main access road. This road appears to be the only access to the eastern field and preexisting to oil and gas.



Photo 2. Looking east across the well location. No oil and gas equipment remains. The northern side of this field including the well area consists of undesirable weedy species such as kochia and russian thistle. There is little to no establishment of desirable vegetation at the time of inspection.



Inspection Photos
Location Name: MURATA #23-19
Location ID: 336442



Photo 3. Looking east from the wellbore. Vegetation consists of undesirable weeds such as kochia and russian thistle. Little to no desirable vegetation is present. The location is mowed.



Photo 4. Looking north from the wellbore area. See photo 3 comments.



Inspection Photos
Location Name: MURATA #23-19
Location ID: 336442



Photo 5. Looking west from the wellbore area. See photo 3 comments.



Photo 6. Looking south from the wellbore area. See photo 3 comments.



Inspection Photos
Location Name: MURATA #23-19
Location ID: 336442



Photo 7. Looking west across the location.



Photo 8. Reference vegetation to the south of the well location. Brome pasture or hay field.



Inspection Photos
Location Name: MURATA #23-19
Location ID: 336442



Photo 9. Google earth aerial imagery taken 2/4/2025. The northern part of the field (red circle) has primarily weedy vegetation compared to the the surrounding field.

